
(a) Startup step 0 → 300 RPM (grey band = ±5 %)
Raw speed (RPM)
Time (s)
A: baseline (Kp 2.63, Ki 12)
(b) Steady state (solid = run 1, dashed = run 2)
Raw speed (RPM)
Time (s)