## InterSpec

Action	Desktop	Mobile
Zoom In Zoom Out	Left-click drag right  * On OSX, you can also three finger drag right  Left-click drag left  * On OSX, you can also three	Move two fingers vertically apart from each other (e.g. pinch out)  Move two fingers vertically towards each other (e.g. pinch
n n alia	finger drag left	in)
Energy Range Shift Energy Range Count	ALT + Left-click drag SHIFT + ALT + Left-click drag	Drag one finger across chart  Drag two vertically aligned fingers over range
Visual Recalibration	Right-click drag * On OSX, change the Secondary Click from "Click or tap with two fingers" to "Click in bottom right corner" in the System Preferences	
Identify Peaks	<ul> <li>Double left-click</li> <li>CTRL + Left-click drag</li> <li>Dock windows, select "Search for Peaks"</li> <li>Dock windows, select "Add"</li> </ul>	<ul> <li>Double tap</li> <li>Drag two horizontally aligned fingers across ROI</li> <li>Dock windows, select "Search for Peaks"</li> <li>Dock windows, select "Add"</li> </ul>
Delete Peaks	<ul> <li>Dock windows, select "Clear all Peaks"</li> <li>SHIFT + Left-click drag over peak</li> <li>Right-click peak, select "Delete Peak"</li> </ul>	<ul> <li>Dock windows, select         "Clear all Peaks"</li> <li>Move two horizontally         aligned fingers up; deletes         all peaks spanned by         fingers.</li> <li>Tap and hold on peak and         select "Delete Peak" from         resulting menu</li> <li>Tap and hold on peak,         select "Peak Editor;" in         Peak Editor select "Delete"</li> </ul>

Shortcut	Action
CTRL + 1	Opens "Spectrum
	Files" tab
CTRL + 2	Opens "Peak
	Manager" tab
CTRL + 3	Opens "Reference
	Photopeaks" tab
CTRL + 4	Opens "Energy
	Calibration" tab
CTRL + 5	Opens "Nuclide
	Search" tab

Problem	Possible Solutions	Other Solution
Trouble fitting New Peak, or many peaks in region	CTRL + Left-click drag over the ROI and select the number of peaks you'de like fit for	<ul> <li>Add a peak using the "Peak Manager" tab, and then manually edit peak parameters</li> <li>Change the continuum type; by default, peaks are assigned Linear continuums.</li> <li>Specify the region of interest (ROI).</li> </ul>
The default peak is near satisfactory, but	<b>Peak Editor</b> ; access the Peak Editor window by right-clicking on a peak and selecting "Peak Editor" from the pop-up menu.	<ul> <li>You can try refitting the peak by right-clicking on it (or touching and holding for a few seconds on mobile) and select "refit"</li> <li>Can manually change parameters using the "Peak Manager"</li> </ul>
		•
		•
		•
		•
		•