Helio Components — supplier quality notice QN-732

Issued 18 October 2026

Supplier lot HELIO-731 has a coating adhesion defect and requires containment review.

Supplier lot HELIO-732 is explicitly excluded from this notice after the separate inspection.

The relationship of lot HELIO-733 to this shipment is unconfirmed; do not exclude it based on this notice.

This is an interim notice. The final incident boundary remains unresolved pending the receiving records.

No customer stock quantities, finished-goods genealogy or order allocations are supplied.

Fictional nonsensitive engineering acceptance document.