

INSPECTION & SERVICE REPORT

Date: 20Juli2018

Customer	PT TANINDO MANDIRI JAYA	Location	Jakarta
Equipment	UG 40 Lever P/N.R 8531 - 888	Serial No	2569487
Checked by	EndarSukandar	Approved by	EndarSukandar

OBSERVATION

Governor : Woodward
TYPE : UG 40 L
Part NO : R 8531-888
Serial No : 2569487

TYPE UG-40
PART NO.
R9837—898
SERIAL NO.
7559487

CUSTOMER NO.


Dismantled Governor



Need to Replace / Damage :

1		Repair Kit
2	03039-114	Base Bearing
3	03039-87	Ballhead Bearing
4	03039-315	Roller Bearing
5	03039-18	Cotter Pin
6	03039-86	Pin

7	03039-109	Washer
8	03039-50	Cotter pin
9	03039-354	PIN
10	03039-002	Drive Shaft
11	03039-01	Gear Shaft Pinion
12	03039-02	Housing Drive Shaft



Reassemble Governor and Calibrated





Assembled Governor

After Assemble and Painted	
Completed	

======== 000 =======