

```
1 physical thermometer(sensor float temperature)
2 with{
3     ctx int altitude = 100; \\ meters
4     SerialPort plug;
5 } init {
6     int red = 0; int blue = 1;
7     int outputColor = red;
8 } then {
9     if (temperature > 30.){
10         outputColor = red;
11     } else{
12         outputColor = blue;
13     }
14 } -> actuator color(outputColor)
15 -> measuredTemp(temperature)
```