## Block commutation

Signal Sequence Design for the Hall Sensors
Conductive phases I II III IV V VI



## Supplied motor voltage (phase to phase)

