



PWR_FLAG
J101
XT60PW-M
1
2
MH1
MH2
3
4
GND
GND
12V_IN_UNPROTECTED
PWR_FLAG
F101
Fuse
PWR_FLAG
12V_IN
C101
10u
GND
Power Measurement1
5V
12V_IN
I2C_SDA1
I2C_SCL1
5V
5V
V_IN
SDA
SCL
A0
A1
V_OUT
F102
Fuse
PWR_FLAG
12V
GND
File: power_measurement.kicad_sch
5V
12V_IN
12V
5V
PWR_FLAG
5V_IN
File: 5V.kicad_sch
Power Measurement
5V
5V_IN
I2C_SDA1
I2C_SCL1
5V
5V
V_IN
SDA
SCL
A0
A1
V_OUT
F103
Fuse
PWR_FLAG
5V
GND
File: power_measurement.kicad_sch
5V
12V
J102
Conn_02x10_Row_Letter_First
12V
5V
a1
a2
a3
a4
a5
a6
a7
a8
a9
a10
b1
b2
b3
b4
b5
b6
b7
b8
b9
b10
I2C_SDA1
I2C_SCL1
GND
GND
+ 5V
C102
100u / 25V
GND
12V
C103
100u / 25V
GND
H101
MountingHole
H102
MountingHole
12V
5V
D101
LED
D102
LED
R101
2k2
R102
1k
GND
GND
Amateurfunkclub für Remote Stationen
Sheet: /
File: PowerBoard.kicad_sch
Title: Power
Size: A4
Date:
Rev: BETA-84e5044
KiCad E.D.A. 9.0.7
Id: 1/4




All CAPS should be of type X7R!

Amateurfunkclub für Remote Stationen		
Sheet: /5V/ File: 5V.kicad_sch		
Title: 5V Buck Converter		
Size: A4	Date:	**Rev: BETA-84e5044**
KiCad E.D.A. 9.0.7		Id: 2/4



Amateurfunkclub für Remote Stationen		
Sheet: /Power Measurement/ File: power_measurement.kicad_sch		
Title: Power Measurement		
Size: A4	Date:	**Rev: BETA-84e5044**
KiCad E.D.A. 9.0.7		Id: 3/4



Amateurfunkclub für Remote Stationen		
Sheet: /Power Measurement1/ File: power_measurement.kicad_sch		
Title: Power Measurement		
Size: A4	Date:	**Rev: BETA-84e5044**
KiCad E.D.A. 9.0.7		Id: 4/4