Date : 16 Sep 2025 Page : 1 of 5

Report Number: SIS2524026 Inspection Date/Time: 16 Sep 2025 13:15

16 Sep 2025 14:00

Workplace: PPT3,PPT2

MOHAMMAD ABDUL RAHIMI BIN RAHMAT, OPS EXEC, YOD, PSA Inspectors:

AUSTIN CHUE, SR OPS EXEC, YOD, PSA

#### **ROADS - TRAFFIC MOVEMENT**

Inspected on: 16 Sep 2025 13:24

#### CheckList

✓ SWP - COMPLIANCE TO TRAFFIC RULES	<b>/</b>	SWP - COMPLIANCE TO TRAFFIC RULES	
-------------------------------------	----------	-----------------------------------	--

Description / Immediate Action	Follow Up / Remarks
The focus of this inspection is to ensure SWP compliance of FMs and PMs.	
Team conducted CCTV inspection to observe compliance to the STOP line along the road between X31 and X09.	
Team observed that PM349 and PM160 came to a complete stop at the STOP line before turning out to the main road.	SWP complied / SBR awarded.
The drivers were commended for complying with SWP and traffic rules.	
They were also reminded to inform Control Centre if they spotted any safety hazards.	



Caption : PM came to a complete stop at the STOP line

#### **Personnel**

Person	Company	NISR / SBR
OWI KIAT CHAI	S M S MARINE PTE LTD	/ SBR Ref No: SBR202509169941
LAKSHMANAN PAZHANIMEGAM		/ SBR Ref No: SBR202509169942

## YARD - PM/HAULIER/IGH OPS


Inspected on: 16 Sep 2025 13:25

#### CheckList

**/** 

SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at FM block T09 to observe the PM queue.	
Team observed PM 602 kept a 40' safety distance from the front PM while queuing for mounting.	SWP complied / SBR awarded.
Team commended the driver for complying with SWP and advised him to report any hazards to Control Centre.	



Caption : PM kept a 40' safety distance from the front  $$\operatorname{PM}$$ 

## Personnel

Person	Company	NISR / SBR
DAHLAN BIN AHMAD	KOON SENG ENTERPRISES PTE LTD	/ SBR Ref No: SBR202509169943

## YARD - HYSTER OPS

Inspected on: 16 Sep 2025 13:30

#### CheckList

✓ SWP COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
Team observed the offloading ops at U31.	
FM 55 operator was observed to wait for the PMs to stop completely before approaching to offload their containers.	SWP complied / SBR awarded.
The FM operator was commended for complying with SWP and was reminded to follow the 3-step hoist when handling containers.	



 ${\it Caption: FM waited for PMs to stop completely before } \\ {\it approaching}$ 

#### Personnel

Person	Company	NISR / SBR
KHALED MOUHSSIN	GKE SERVICES PTE LTD	/ SBR Ref No: SBR202509169944


#### **YARD - HYSTER OPS**

Inspected on: 16 Sep 2025 13:33

## CheckList

✓ SWP COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at FM block L10.	
Team observed that FM 54 operator had the spreader retracted to 20' and held at 3-high while on standby.	SWP complied / SBR awarded.
The operator was commended for complying with SWP and was reminded to inform Control Centre if he needed to take a bathroom break.	



Caption: FM 54 on standby

## Personnel

Person	Company	NISR / SBR
SAZALI BIN ABDUL RAHMAN	GKE SERVICES PTE LTD	/ SBR Ref No: SBR202509169945