Date: 12 Sep 2025

Page: 1 of 6

Report Number: SIS2523636 Inspection Date/Time: 12 Sep 2025 11:45

12 Sep 2025 14:15

Workplace: PPT1,PPT2,PPT3

Inspectors: MOHAMMAD ABDUL RAHIMI BIN RAHMAT, OPS EXEC, YOD, PSA

REYNILDA RAHAYU BINTE OSMAN, SR OPS EXEC, YOD, PSA MUHAMMAD JAMALULLAIL BIN MAHADI, SR OPS EXEC, YOD, PSA

YARD - CO2 - GENERAL

Inspected on: 12 Sep 2025 11:55

CheckList

×

PPE COMPLIANCE

Description / Immediate Action	Follow Up / Remarks
The focus of this inspection is to observe IPM and PM compliance to SWP in the yard.	
At about 1157hrs, the driver of IPM 093 was observed coming down from his IPM cabin without wearing proper PPE.	NISR issued.
His reflective vest was not zipped up and he was wearing sports shoes instead of safety shoes.	



Caption: Engagement with driver of IPM 093

YARD - E01 - PM/HAULIER/IGH OPS

Inspected on: 12 Sep 2025 12:10

CheckList

✓ SWP COMPLIANCE (HAULIERS/IGH) - LOCKING AND UNLOCKING OF TRAILER TWISTLOCKS

Description / Immediate Action	Follow Up / Remarks
Team proceeded to engage with driver of IPM 123 at BC block E01.	
Driver was observed to stop at a safe location to secure the trailer twistlocks.	SWP complied / SBR awarded.
Driver was commended for complying with SWP and was reminded to report any hazards to his supervisor / controller.	



Caption: Engagement with IPM driver

Personnel

Person	Company	NISR / SBR
CHEONG CHOW CHUEN	MAKEWAY PACIFIC P L	/ SBR Ref No: SBR202509129817

YARD - PM/HAULIER/IGH OPS

Inspected on: 12 Sep 2025 12:30

CheckList

V

SWP COMPLIANCE (HAULIERS/IGH) - LOCKING AND UNLOCKING OF TRAILER TWISTLOCKS

Description / Immediate Action	Follow Up / Remarks
Team proceeded to engage with driver of IPM 796 at EARTG block K09.	
Driver was observed to stop at a safe location to unlock the trailer twistlocks.	SWP complied / SBR awarded.
Driver was commended for complying with SWP and was reminded to drive safely and inform his controller if he needed to take a break or freshen up.	



Caption: Engagement with IPM driver

Personnel

Person	Company	NISR / SBR
GOH HOCK MENG	S M S MARINE PTE LTD	/ SBR Ref No: SBR202509129818

ROADS - M10 - PM OPS

Inspected on: 12 Sep 2025 14:00

CheckList

✓ SWP - COMPLY WITH TRAFFIC RULES

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at RTG block M10.	
Team observed that PM 8429 came to a complete stop at the STOP line at the end of the block.	SWP complied / SBR awarded.
Team commended the driver for complying with traffic rules and reminded the driver to work safe and report any hazards to the supervisor / control centre.	



Caption : PM came to a complete stop at the STOP line

Personnel

Person	Company	NISR / SBR
LU CHEE LOON		/ SBR Ref No: SBR202509129819

YARD - PM/HAULIER/IGH OPS


Inspected on: 12 Sep 2025 14:05

CheckList

/

SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING

Description / Immediate Action	Follow Up / Remarks
Team conducted CCTV inspection at FM block T31 on the PMs queueing for mounting.	
PM 503 was observed to comply with a 40' safety distance from front PM while waiting for his turn.	SWP complied / SBR awarded.
The PM driver was commended for complying with SWP and was reminded to stay alert and work safe at all times.	



Caption : PM kept a 40' safety distance from the front

Personnel

Person Company NISR / SBR	
---------------------------	--

MURUGAN KANNADASAN	HOY DW PTE. LTD.	/ SBR Ref No: SBR202509129820
--------------------	------------------	-------------------------------