Date: 22 Sep 2025 Page: 1 of 4

Report Number: SIS2524548 Inspection Date/Time: 21 Sep 2025 22:00

22 Sep 2025 03:00

Workplace: PPT2,PPT3,PPT1

Inspectors: MUHAMMAD JAMALULLAIL BIN MAHADI, SR OPS EXEC, YOD, PSA

AUSTIN CHUE, SR OPS EXEC, YOD, PSA


# YARD - T09 & X31 - PM/HAULIER/IGH OPS

Inspected on: 21 Sep 2025 22:54

### CheckList

<b>✓</b>	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
<b>~</b>	SWP COMPLIANCE - OBEY TRAFFIC RULES (STOPPED BEFORE WHITE STOP LINE BEFORE PROCEEDING TO NEXT LOCATION)

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at FM yard blocks to check on PPMs compliance to SWP.	
-Firstly, It was observed that PPM 8325 stopped before the STOPLINE at the end of T09 before proceeding to his next location.	
- Next, It was observed that PPM 605 was observed to be maintaining 2X20 footer safety distance from the front PM while awaiting his turn to mount at FM yard X31.	SWP Complied/SBR issued.
-Both PPM driver 8325 & 605 was commended for complying to SOPs and for continuing to always practice safe driving habits.	
-Both PPM driver 8325 & 605 was reminded to report any hazards immediately to control center.	



Caption: PM 8325 stopped at the STOP LINE at the end of L11 checked for clear traffic before moving off.

Caption: PPM 605 MAINTAIN 1X 40FT SAFETY DISTANCE at X31

### **Personnel**

Person Company NISR / SBR
---------------------------

SIVAJI GNANESH	CALL LADE ENTERPRISES PTE LTD	/ SBR Ref No: SBR2025092210113
ONG WOOI CHAI		/ SBR Ref No: SBR2025092210114

### YARD - CHASSES LANE OF RMG BLOCK A13 - PM/HAULIER/IGH OPS

Inspected on: 21 Sep 2025 22:25

### CheckList



SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING

Description / Immediate Action	Follow Up / Remarks
-Team conducted a CCTV inspection at PPT1 RMG yard.	
At about 2225hrs, it was observed HOY SAN IPM770 driver, failed to keep 40ft safety distance from front PM while queueing inside the yard at A13.	SWP not complied/ NISR S2025005284 issued.



Caption: IPM 770 failed to maintain 1X40 footer safety distance from front PM

## **YARD - X31 - HYSTER OPS**

Inspected on: 21 Sep 2025 23:38

### CheckList

**V** 

FM Stopped before the white line and checked traffic clearance before reversing out from the yard slot

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at FM yard X31 to check on FM compliance to SWP.	
- At FM yard X31, FM038 was observed to have came to a complete stop before the white line and check for	
traffic before further moving out from the yard slot.	SWP Complied/SBR issued.
-Team commended FM 038 for complying to SWP and	
also reminded the FM operators to report any hazard immediately to his superiors and/or control centre.	



Caption: FM 038 stopped white line before reversing

### **Personnel**

Person	Company	NISR / SBR
SUBASH S/O CHATHOO	S M S MARINE PTE LTD	/ SBR Ref No: SBR2025092210115

### **YARD - U31 - HYSTER OPS**

Inspected on: 22 Sep 2025 01:49

### CheckList

**V** 

FM gantry followed SWP aspects with spreader raised to 3 high and closed to 20 footer

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at FM yard U31 to check on FM compliance to SWP.	
- At FM yard U31, team observed FM051 operator adhered to SOP when gantrying from smaller to bigger slot with 20 footer spreader close and raised to 3 high.	SWP Complied/SBR issued.
-Team commended FM051 operator for complying to SWP and also reminded the FM operators to report any hazard immediately to his superiors and/or control centre.	



Caption: FM 051 gantry followed SWP aspects with spreader raised to 3 high and closed to 20 footer

### **Personnel**

Person	Company	NISR / SBR
MUHAMAD FAIZ BIN MOHD ZAM	GKE SERVICES PTE LTD	/ SBR Ref No: SBR2025092210116

### **YARD - Street of XY - YC GANTRY**


Inspected on: 22 Sep 2025 02:30

# CheckList

**/** 

SWP COMPLIANCE - LINEAR AND CROSS GANTRY

Description / Immediate Action	Follow Up / Remarks
Team then conducted inspection at Terminal 3 RTG yard blocks to ensure that RTG operators ensure traffic clearance and no obstruction at the gantry path before proceed out from the RTGs block.	SWP Complied/SBR issued.



Caption : RTG 363 ensure traffic clearance during gantry operation

# Personnel

Person	Company	NISR / SBR
SUDIRMAN BIN ROSIDI		/ SBR Ref No: SBR2025092210117