

Site:		Tai	nRo,	Beau	uchar	mp Business Park. Kibworth, Leics, LE08 0RX	As	ses	smer	nt Nu	ımber RA 154	
Task / Activity		Pa	rtitior	ning,	Plast	er boarding and Tape and jointing.						
Date Conducted		24-	-11-2	2023		Date Reviewed						
Assessment Team	1	DD	)/JW				Ch	eck	ed ar	nd A	pproved by: DD	
<b>1</b> Hazard	2 Hazard Effect	3 At Risk	4 Severity	<b>5</b> Probability	6 Risk Rating	7 Required Control Measures (minimum requirements)	8 Severity	9 Probability	10 Risk Rating	11 Acceptable?	Additional Controls to Reduce Risk Further	13 Completed
Falls From Height using hop-ups	Falls leading to death, broken bones, fractures etc.	E	4	3	1 2	<ul> <li>ALWAYS look to work from the ground where reasonably practical to do so.</li> <li>Ensure hop-ups are inspected by competent person.</li> <li>Ensure employees are trained and competent in use of equipment.</li> <li>Ensure employees are wearing suitable safety boots.</li> <li>Ensure hop-ups are clean and free from plaster/paint/grease etc.</li> <li>Ensure equipment is not used in roads or pathways without suitable protective barriers.</li> <li>Use 600x600 hop ups for stability</li> <li>Ensure you only work from completed load bearing floors.</li> <li>Never work next to openings in floors.</li> <li>Report any faults immediately.</li> </ul>	4	2	8	M	Reinforce with regular toolbox talks regarding safe work at height.	

At Risk	Sev	verity	Pro	bability	Risk Rating	Risk Rating							
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable						
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required						
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	<b>U</b> – Unacceptable Risk						
P - Public	4	Major Injury	4	Very Likely									
A - All	5	Death	5	Virtually Certain									



Use of Tower	Falls	-	F	1	2		Francisco that the terror is af a district and a set	F	1	F	Λ		Delafance with near least called the literature of the least of the le	T
Scaffolds	leading to	E	5	4	2	•	Ensure that the tower is of suitable size and construction for the task.	5	1	5	Α	•	Reinforce with regular toolbox talks regarding safe work at height.	
Scariolus	death,				0		Ensure the tower is erected and inspected by a PASMA						neight.	
	broken					Ι'	trained worker.							
	bones.					I.	Only use on flat, level ground.							
	fractures					I.	Check overhead hazards before starting work.							
	etc.					I.	Ensure all components are used including outriggers							
						ľ	and kickboards.							
						١.	Ensure towers are only erected on flat stable ground.							
						I.	Ensure internal access is used – do not climb up the							
						ľ	outside of tower.							
						١.	Never use close to overhead power cables.							
						Ι.	Ensure the tower is tagged and inspected before use.							
							Ensure other workers are restricted from entering the							
							area – set up barriers.							
							Ensure PPE is worn including safety helmets.							
							NEVER move a tower with a person on the structure.							
							Always use wheel locks.							
							Ensure outriggers are always used.							
							Ensure all components are used.							
							Read manufacturer's instructions before use.							
						•	Barrier off in busy areas.							
Use of Stepladders	Falls	Е	5	4	2	•	ALWAYS look to work from the ground where					•	Reinforce with regular toolbox talks regarding safe work at	
	leading to				0		reasonably practical to do so.						height.	
	death,					•	STEPLADDERS ONLY USED WHERE THERE IS NO							
	broken						SAFER ALTERNATIVE AND A PERMIT MUST BE							
	bones,						OBTAINED FROM TANRO SITE MANAGER.							
	fractures					•	Ensure steps are industrial class and of adequate							
	etc.						strength and height							
						•	Only use on flat, level ground.							
						•	Ensure steps are inspected by competent person before							
							use and DO NOT use defective steps.							
						1.	Ensure employees are trained and competent in use of							
							equipment.							
						1.	Ensure employees are wearing suitable safety boots. Ensure steps are clean and free from							
						Ι'	plaster/paint/grease etc.							
						١.	Ensure equipment is not used in roads or pathways							
						1	without suitable protective barriers.							
						1.	Ensure 3 points of contact at all times.							
						1.	DO NOT use the top 3 steps							
						1.	Only carry out very light work for short periods.							
						1.	DO NOT lean out of the side of the steps.							
Ц	1						DO 110 1 loan out of the side of the stops.							

At Risk	Sev	erity/	Pro	bability	Risk Rating	Risk Rating						
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable					
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required					
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	<b>U</b> – Unacceptable Risk					
P - Public	4	Major Injury	4	Very Likely								
A - All	5	Death	5	Virtually Certain								



Steps le	Falls eading to death, broken bones, ractures etc.	Ш	5	3	5	<ul> <li>ALWAYS look to work from the ground where reasonably practical to do so.</li> <li>Ensure podiums are of adequate strength and height.</li> <li>Only use on flat, level ground.</li> <li>Ensure podiums are inspected by competent person before use and DO NOT use defective podiums.</li> <li>Ensure employees are trained and competent in use of equipment.</li> <li>Ensure employees are wearing suitable safety boots.</li> <li>Ensure podiums are clean and free from plaster/paint/grease etc.</li> <li>Ensure equipment is not used in roads or pathways without suitable protective barriers.</li> <li>Ensure gate is always closed when on the platform.</li> <li>Ensure brakes/outriggers are always used.</li> <li>DO NOT climb on rails to gain extra height.</li> <li>DO NOT lean out of the side of the podiums.</li> </ul>					
Elevating Work Platforms (MEWP's)	Death, proken pones, ractures etc.	E	5	4	2 0	<ul> <li>BO NOT lean out or the side of the podiums.</li> <li>Ensure MEWP is fit for purpose and suitable for the application and environment.</li> <li>Only use on flat stable ground.</li> <li>Ensure MEWP's are only used by IPAF Qualified workers.</li> <li>Ensure MEWP's are subject to daily pre-use checks.</li> <li>Ensure outriggers are used.</li> <li>Ensure that the area below is cordoned off with plastic barriers or cones / visible tape.</li> <li>Do not use in areas where the MEWP may be struck by a vehicle or plant.</li> <li>DO NOT use in windy conditions – check wind speed if in doubt.</li> <li>DO NOT use near power lines or in proximity to overhead hazards.</li> <li>DO NOT use steps or hop ups to gain extra height on the platform.</li> <li>Ensure the MEWP is serviced and maintained.</li> <li>Ensure the MEWP is subject to 6 monthly Thorough Examinations.</li> <li>DO NOT use the MEWP for lifting heavy objects such as large quantities of plasterboard.</li> <li>Only use in accordance with training.</li> <li>Ensure a rescue plan is documented.</li> <li>Ensure harnesses are used and workers trained in the use and inspection of harnesses.</li> <li>Ensure that while diesel MEWP is in operation within the building, level access doors will be kept open for ventilation purposes and closed at end of shift.</li> </ul>	5	1	5	A	Reinforce with regular toolbox talks regarding safe work at height.

At Risk	Sev	erity/	Pro	bability	Risk Rating	Risk Rating							
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable						
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required						
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	<b>U</b> – Unacceptable Risk						
P - Public	4	Major Injury	4	Very Likely									
A - All	5	Death	5	Virtually Certain									



Falling Objects	Head injuries, cuts etc.	A	3	3	9	Ensure that no objects are stored on access equipment platforms.      Wear tool belt as opposed to carrying tools.      Make other employees/contractors aware of your work.     Ensure that access equipment is not left unattended.      Ensure that all plasterboards are securely fixed to ceilings and walls before being left unattended.      Ensure that public or adjacent workers are not permitted.	3	3 A	•	Reinforce with regular toolbox talks regarding falling objects and materials.
Contact with electricity from tools and cable strike	Electric Shock, burns	E	5	3	15	<ul> <li>in the work area</li> <li>Ensure that all electrical tools and equipment are visually inspected prior to use and any defects reported prior to use.</li> <li>Ensure only battery rechargeable or 110v equipment used on site.</li> <li>Ensure all portable appliances are PAT tested at 3 monthly intervals.</li> <li>Ensure employees are trained and competent.</li> <li>Ensure that service plans are obtained where available and that walls / ceilings etc. are CAT scanned for cables and wires prior to any fixing work.</li> <li>DO NOT drill if power cables are suspected.</li> <li>Isolate power sources where possible to reduce risk further.</li> <li>Clearly, mark cable runs etc. on the wall.</li> </ul>		5 A	•	Reinforce with regular toolbox talk regarding contact with live services Periodic site inspections to ensure all the appropriate steps have been followed
Vibration from hand operated power tools	Hand arm vibration syndrome, vibration white finger	E	4	2	8	<ul> <li>Ensure that vibration damped equipment is specified wherever possible.</li> <li>Ensure that jobs using vibrating tools are rotated amongst the team.</li> <li>Ensure that tools and equipment are well maintained and any defects reported immediately.</li> <li>Ensure operatives are wearing gloves in cold weather.</li> <li>Issue HAVS questionnaire to employees.</li> </ul>	2	1 A	•	Reinforce with regular toolbox talks regarding hand arm vibration. Carry out trigger time survey. Ensure that vibration data is explained to employees as part of the toolbox talk
Noise	Hearing loss, tinnitus etc.	A	3	3	9	Ensure that noise damped tools are specified wherever possible.     Ensure that ear defenders are formally issued and employees instructed to use them when using power tools.     Ensure that adjacent workers are instructed of times when noisy activities will be undertaken to ensure they are not in the working area.     Ensure that tools and equipment are well maintained and any defects reported immediately.	3	3 A	•	Reinforce with regular toolbox talks.

At Risk	Sev	erity/	Pro	bability	Risk Rating						
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable				
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required				
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	<b>U</b> – Unacceptable Risk				
P - Public	4	Major Injury	4	Very Likely							
A - All	5	Death	5	Virtually Certain							



П				1 -	1 -	
Hazardous Substances	Skin, eye, lung irritation etc.	A	3	2	6	<ul> <li>Ensure employees are taken through COSHH assessments and understand how to use substances.</li> <li>Ensure suitable approved gloves, eye protection and FFP3/P3 respirators are available, with face fit testing.</li> <li>Ensure that only the minimum amount of substances are used and stored on site / in vehicles.</li> <li>Ensure that substances are kept in original containers.</li> <li>Ensure glues etc. are used in guns to limit potential for skin exposure.</li> <li>Ensure operators know the risks of dry plaster powder and know to avoid skin contact, excessive dust build-up and contact with eyes.</li> <li>Work area suitable to prevent excessive dust build-up, well ventilated.</li> <li>Minimal quantities used, due to small area to be plastered.</li> <li>Water supply, toilets, available nearby to wash dust off skin.</li> <li>Operators keep work area clean.</li> <li>Gloves and barrier creams available.</li> </ul>
Exposure to dust from cutting plaster boards	Industrial Asthma, respiratory disease.	Е	3	3	9	Ensure that suitable face fitted P3 or FFP3 approved respirators are worn when generating dust.     Ensure dust is vacuumed as opposed to swept with M or H Class vacuums.     Ensure plasterboard is hand cut as opposed to sawn.     Cutting station used for cutting metal partition components;      Ensure that all plasterboard is scored and cut by hand outside wherever possible.     Ensure routing tools are used with on-tool extraction.      Reinforce with regular toolbox talks regarding dust exposure Ensure workers that require a face-mask are face-fit tested     Health surveillance for those exposed to dust.     See Silica COSHH Assessment.     Issue the health questionnaire regarding lung function to your employees and review the feedback

At Risk	Sev	erity/	Pro	bability	Risk Rating						
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable				
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required				
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	U – Unacceptable Risk				
P - Public	4	Major Injury	4	Very Likely							
A - All	5	Death	5	Virtually Certain							



Manual Handling	Back	E	3	3	9	Plasterboard will be loaded out to each floor by site	3	2	6	М	•	Refresh manual handling training at 3-5 year intervals for all
Plaster Board	injuries,					team, to designated areas.						employees
	strains etc.					Starke Arvid lift truck and trolley to be used to distribute					•	Refer to specific manual handling assessments for moving
						plasterboard throughout the project (See method						plasterboard and rockwool insulation
						statement).						
						Ensure employees are trained in manual handling						
						techniques.						
						Ensure that the site is assessed prior to arrival to identify						
						a suitable parking area as close to the site as possible to						
						reduce carrying distance.						
						Ensure work area is cleared prior to work commencing     to reduce risk of align / trips ata						
						to reduce risk of slips / trips etc.						
						Ensure only one board carried at a time by two persons where the trolleys cannot be used.						
						Use palletised plasterboard delivered direct to site. This						
						can be offloaded with a Forklift truck						
						Use grab handles for moving plasterboard from the						
						trolley to fitting area.						
Slips and trips	Cuts,	Е	3	3	9	Walk around work areas prior to unloading vehicle to	3	1	3	Α	•	Reinforce with regular toolbox talks.
	bruises,					identify suitable storage locations etc.						
	broken					Identify points of access and egress prior to works						
	bones etc.					commencing.						
						Ensure any water spillages are kept to a minimum and						
						cleared up as soon as practical – highlight slippery floors						
						with signs						
						Plan the works to limit the need to trail cables / block						
						walkways etc.						
						Ensure that no tools or equipment is left in walkways						
						etc.						
						Ensure that workers are equipped with suitable safety						
						boots.						
						Ensure that work areas remain tidy and any waste etc. is						
						removed to suitable skip as soon as practical						

At Risk	Sev	erity/	Pro	bability	Risk Rating						
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable				
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required				
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	<b>U</b> – Unacceptable Risk				
P - Public	4	Major Injury	4	Very Likely							
A - All	5	Death	5	Virtually Certain							



Handling MMMF Rockwool Insulation  Indus Asthr respir disea	ma, ratory	E	4	3	12	<ul> <li>Refer to COSHH Assessment for MMMF Rockwool</li> <li>Refer to Manual Handling Assessment MHA 001 MMMF Rockwool</li> <li>If not conducted in a well ventilated area an FFP3/P3 disposable mask is recommended</li> </ul>	4	2	8	M	•	Reinforce with regular toolbox talks regarding dust exposure Ensure workers that require a face-mask are face-fit tested Health surveillance for those exposed to dust. Issue the health questionnaire regarding lung function to your employees and review the feedback
i.e. circular saw nt, ele shock	ectric	E	4	2	8	<ul> <li>Ensure that tools supplied are suitable and adequate for the job.</li> <li>Cutting station used for cutting metal partition components;</li> <li>Ensure employees are trained and competent in the use of the equipment.</li> <li>Ensure all equipment is visually checked prior to use and defects reported before use.</li> <li>Ensure only battery rechargeable or 110v equipment used.</li> <li>Ensure electrical equipment is PAT tested.</li> <li>Ensure all guards and safety devices are in place before use.</li> <li>Ensure disc is in good condition and not damaged.</li> <li>Ensure employees wear suitable safety boots, hardhat, impact eye protection, ear defenders and an approved mask/respirator – see dust.</li> <li>Ensure equipment is used with on-tool extraction system.</li> </ul>	4	1	4	A	•	Reinforce with toolbox talk regarding use of power tools

At Risk	Sev	erity/	Pro	bability	Risk Rating	Risk Rating						
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable					
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required					
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	<b>U</b> – Unacceptable Risk					
P - Public	4	Major Injury	4	Very Likely								
A - All	5	Death	5	Virtually Certain								



Use of Spit Nail Guns	Puncture wounds, eye injuries etc.	E	5	3	15		Ensure that nail guns supplied are suitable and adequate for the job.  Ensure employees are trained and competent in the use of nail guns.  Ensure all equipment is visually checked prior to use and defects reported before use.  Ensure cartridges are taken off site for suitable disposal.  Ensure all guards and safety devices are in place before use.  Display warning signs when equipment is being used.  Ensure no loose clothing / jewellery / long hair is worn.  Ensure only approved nails and fixings are used.  Ensure employees wear suitable impact eye	5	1	5	Α	•	Reinforce with toolbox talks.	
Sanding Taped Plasterboard Joints	Lung disease, dust exposure, hand arm vibration.	Е	4	3	12	•	Ensure employees wear suitable impact eye protection. Ensure job rotation is employed to reduce HAVS exposure. Ensure nail guns are serviced and well maintained. Ensure that sanders are fit for purpose. Sanders only to be used in conjunction with on-tool extraction system (M or H Class vacuum). Ensure that workers are wearing face fit tested P3 or FFP3 respirators or air fed masks. Exclude none essential personnel. Ensure job rotation is employed to reduce HAVS exposure. Ensure suitable sanding discs are used and changed regularly to reduce dust exposure. Use door guards where possible to prevent the spread of dust throughout the project.	4	1	4	Α	•	Reinforce with toolbox talks.	

At Risk	Sev	erity/	Pro	bability	Risk Rating					
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable			
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required			
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	U – Unacceptable Risk			
P - Public	4	Major Injury	4	Very Likely						
A - All	5	Death	5	Virtually Certain						



Cutting Plywood Sheets	Cuts, amputations, dust exposure etc.	Е	4	3	12	<ul> <li>Ensure suitable jigsaw is used (Battery rechargeable).</li> <li>Ensure workers are trained and competent.</li> <li>Ensure wood is cut on suitable workbench/trestles.</li> <li>Ensure saws are used with on-tool extraction systems.</li> <li>Ensure dust residues are vacuumed with an M-Class vacuum.</li> <li>Ensure P3/FFP3 respirator is worn.</li> <li>Ensure ear defenders and safety goggles are worn.</li> <li>Ensure blades are sharp and are changed regularly.</li> </ul>	4	1	4	A	Reinforce with toolbox talks.	
Authorised by The Responsible Manager			Sigr	ned:			Dat	ed:				

At Risk	Sev	erity/	Pro	bability	Risk Rating					
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable			
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required			
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	U – Unacceptable Risk			
P - Public	4	Major Injury	4	Very Likely						
A - All	5	Death	5	Virtually Certain						



	-		

At Risk	Sev	erity	Pro	bability	Risk Rating					
E - Employees	1	No Injury	1	Very Unlikely	1 – 5	LO W	A - Acceptable			
C - Contractors	2	Minor Injury	2	Unlikely	6 - 14	MEDIUM	M - More Analysis Required			
V - Visitors	3	+3 Day Absence	3	Likely	15 - 25	HIGH	U – Unacceptable Risk			
P - Public	4	Major Injury	4	Very Likely						
A - All	5	Death	5	Virtually Certain						