

\* DP sensor needs 5V unlike the controller and other sensors that need 3.3. Have to power with a 2nd usb cord. Stemma connectors have voltage regulation so this wont damage the other sensors.