

Site B — Hydraulics Laboratory: Annual Safety and Training Report

Site B houses the hydraulics laboratory used for pressure-system training. Because the laboratory works at higher stored energies than the general workshop, its induction is longer and its incident threshold is lower.

Recorded figures

Quarter	Incidents	Training hours
Q1	9	160
Q2	6	155
Q3	4	180
Q4	4	175

Commentary

Two of the incidents recorded in the first quarter involved hose failures on the older test rig, which has since been replaced. The remaining incidents were minor fluid contact events with no injury. Training hours include the mandatory eight-hour pressure-system induction taken by every new learner before any independent work is permitted.



Figure 1: Pressure test rig, isolation valve positions.

Inspection outcome

The replacement of the older test rig in the second quarter is the most likely explanation for the reduction in the second half of the year, but no controlled comparison was performed and this should be read as an observation rather than a finding.