

Site A — Metal Workshop: Annual Safety and Training Report

Site A operates a metal workshop used by first- and second-year apprentices in machining and welding. This report covers the four quarters of the reporting year and summarises recorded incidents, delivered training hours and the outcome of the annual equipment inspection.

Recorded figures

Quarter	Incidents	Training hours
Q1	7	120
Q2	5	140
Q3	3	210
Q4	2	195

Commentary

Incident recording follows the workshop's standing procedure: every event requiring first aid or causing an interruption of more than fifteen minutes is logged, whether or not an injury resulted. Training hours count only supervised practical instruction; theory hours are recorded separately and are not included here. The rise in training hours in the third quarter reflects the introduction of the revised hot-work induction.



Figure 1: Layout of the welding bays and extraction points.

Inspection outcome

The annual inspection recorded two non-conformities, both relating to extraction airflow in bays three and four. Both were closed before the end of the year. No equipment was withdrawn from service.