

True original-bond events mapped to reference q · reference coordinates


U · Uniform reference
first softening





U · Uniform reference
first failure





U · Uniform reference
final





H · Correlated softening
first softening




H · Correlated softening
first failure




H · Correlated softening
final




Green: displayed live nearest bonds; dashed red: naturally failed nearest bonds; orange: actual event bonds (all lengths). Connectivity always uses all bonds.