


04 WALL audit — zero is measured, not assumed

All WALL node components are exactly zero



No leakage through the real slab side WALL

