




2.0 mm/s + P9-A | Smoke batch failed the production gate



12 integrated: 5 outlet exits · 2 inlet escapes · 4 subdivision progress stops · 1 time-limit stop
500-track production was not launched. No observed WALL penetration; upstream cap escape is a separate failure.