
C5: no stability loss found at the audited states
Minimum Schur curvature (stable certificate)
AT1 activation bracket
All mechanical blocks are positive definite
S0 has no movable phase DOF
Stop: max phase crosses 0.10
Dimensionless phase-condensed curvature
0.0025
0.0020
0.0015
0.0010
0.0005
0.0000
0.004500
0.004525
0.004550
0.004575
0.004600
0.004625
0.004650
0.004675
0.004700
Engineering strain