Undegraded active energy fraction on accepted coupled states
Psi plus / (Psi plus + Psi minus)
1.0000
0.9995
0.9990
0.9985
0.9980
0.9975
0.9970
0.9965
C7 coupled branch: NOT RUN
C5 stops before accepted phase activation
C3: accepted branch states
C5: accepted branch states
0.000
0.002
0.004
0.006
0.008
0.010
Engineering strain