
Pre-relaxation: damage = 0 and exposure = 0 throughout
EROSION CLOCK STARTS HERE: after iteration 450 passes every criterion
Numerical motion diagnostic
Pseudo kinetic measure (not physical energy)
ADR iteration
Free-particle residual
Relative force residual
ADR iteration
Maximum tensile strain
1e−4
Tensile strain
ADR iteration