
Staggered convergence and the failed robustness check
Monotonic cube: last accepted step
Loading path: failed step
Extra iterations: failed step
Acceptance tolerance
Post-phase force residual
Maximum phase increment
Staggered iteration within the load step
0
5
10
15
20
25