

Figure A.2 Format of the entire LC-3 instruction set. Note: + indicates instructions that

Address	I/O Register Name
XFE00	Keyboard status register
XFE02	Keyboard data register
XFE04	Display status register
XFE06	Display data register
XFFFE	Machine control register
XFFFC	Process status register

Trap Vector	Assembler Name
X20	GETC
X21	OUT
X22	PUTS
X23	IN
X24	PUTSP
X25	HALT

Binary	Hex	Decimal
0000	0	0
0001	1	1
0010	2	2
0011	3	3
0100	4	4
0101	5	5
0110	6	6
0111	7	7
1000	8	8
1001	9	9
1010	Α	10
1011	В	11
1100	С	12
1101	D	13
1110	Е	14
1111	F	15

Char	Dec	Oct	Hex	Char	Dec	Oct	Hex	Char	Dec	Oct	He
(sp)	32	0040	0x20	@	64	0100	0x40	1.	96	0140	0x
1	33	0041	0x21	A	65	0101	0x41	a	97	0141	0x
**	34	0042	0x22	В	66	0102	0x42	l b	98	0142	0x
#	35	0043	0x23	C	67	0103	0x43	C	99	0143	0x
5	36	0044	0x24	D	68	0104	0x44	d	100	0144	0x
96	37	0045	0x25	E	69	0105	0x45	e	101	0145	0x
&	38	0046	0x26	F	70	0106	0x46	l f	102	0146	0x
•	39	0047	0x27	G	71	0107	0x47	l g	103	0147	0x
(	40	0050	0x28	Н	72	0110	0x48	l h	104	0150	0x
()	41	0051	0x29	1	73	0111	0x49	l i	105	0151	0x
*	42	0052	0x2a	J	74	0112	0x4a	l i	106	0152	0x
+	43	0053	0x2b	K	75	0113	0x4b	l k	107	0153	0x
,	44	0054	0x2c	L	76	0114	0x4c	11	108	0154	0x
-	45	0055	0x2d	M	77	0115	0x4d	m	109	0155	0x
	46	0056	0x2e	N	78	0116	0x4e	n	110	0156	0x
1	47	0057	0x2f	0	79	0117	0x4f	0	111	0157	0x
0	48	0060	0x30	P	80	0120	0x50	p	112	0160	0x
1	49	0061	0x31	Q	81	0121	0x51	l q	113	0161	0x
2	50	0062	0x32	R	82	0122	0x52	1	114	0162	0x
2	51	0063	0x33	S	83	0123	0x53	S	115	0163	0x
4	52	0064	0x34	T	84	0124	0x54	t	116	0164	0x
5	53	0065	0x35	U	85	0125	0x55	u	117	0165	0x
6	54	0066	0x36	V	86	0126	0x56	V	118	0166	0x
7	55	0067	0x37	W	87	0127	0x57	W	119	0167	0x
8	56	0070	0x38	X	88	0130	0x58	X	120	0170	0x
9	57	0071	0x39	Y	89	0131	0x59	l y	121	0171	0x
;	58	0072	0x3a	Z	90	0132	0x5a	Z	122	0172	0x
;	59	0073	0x3b	]	91	0133	0x5b	1 {	123	0173	0x
<	60	0074	0x3c	1	92	0134	0x5c	11	124	0174	0x
=	61	0075	0x3d	]	93	0135	0x5d	1 }	125	0175	0x
>	62	0076	0x3e	٨	94	0136	0x5e	-	126	0176	0x
?	63	0077	0x3f	_	95	0137	0x5f				