




↳ High thermal
expansion coef
material.

In tool box, we heat the metal
it expands. Arm enters the cavity. stop
heating, tool side shrink. Rock
solid connection ✓