


Phase Fractions during Cooling ($C_0 = 40\% \text{ Ni}$)



Lever Rule: $W_L = 38.5\%$, $W_\alpha = 61.5\%$

