Sheet1

NC O

NC 🔘

פנד 🔾

O vas

v c c S D A

P W

1 2 C

c


2 C

s


D

G N P W 2 C 1 2 C





DEFAULT	PORT	ADC	PWM
RI	NC		
DCD	NC		
DSR	NC		
DTR	NC		
RTS	NC		
стѕ	NC		
RXD	NC		
TXD	NC		
SCL	SCL		
SCL	SCL		
SDA	SDA		
5.0 VOLTS	5V0		
GND	GND		





PatternAgents
http://github.com/thingsoc/
TSOC_GROVEY_I2CHUB