

SITE MAINTENANCE LOG -- TOWER RIDGE CORRIDOR

Site B -- Segment 9 (Pole TR-38 to JB-9B) | Log Period: 2026-Q2

LOG-TR-2026-Q2

MAINTENANCE ACTIVITY LOG

Date	Time	Tech	Activity	Duration	Sign-Off
04/10	08:00	Alvarez	Full corridor walk + photo	6.5h	[signed]
04/10	08:00	Alvarez	Video documentation (incl.)	(incl.)	[signed]
04/15	14:30	Sharma	Follow-up walk + strand check	3.0h	[signed]
04/15	15:00	Sharma	Barrier reinstallation	0.5h	[signed]
04/20	09:00	Team C	Survey walk (Steps 1,3)	4.0h	[signed]
04/22	07:00	Team A	OTDR testing all routes	5.5h	[signed]
04/22	13:00	Team A	Emergency splice Str 7,11	3.5h	[signed]
04/28	08:30	Nakamura	Engineering assessment	4.0h	[signed]
04/28	08:30	Sharma	Splice verification	3.0h	[signed]
05/02	07:30	Alvarez	Post-storm inspection	5.0h	[signed]
05/02	14:00	Team A	Emergency barrier repair	2.0h	[signed]
05/05	09:00	GeoCorp	Vault measurement update	3.0h	[ext. sign]

LABOR SUMMARY -- REACTIVE MAINTENANCE

Crew/Person	Hours Q2	Rate	Cost	Budget Code
Alvarez (Inspector)	14.5	\$85/h	\$1,233	INSP-TR-Q2
Sharma (Field Tech)	11.0	\$95/h	\$1,045	TECH-TR-Q2
Team A (Fiber Crew)	11.0	\$180/h	\$1,980	CREW-TR-Q2
Team C (General)	4.0	\$120/h	\$480	CREW-TR-Q2
Nakamura (Engineer)	4.0	\$150/h	\$600	ENG-TR-Q2
GeoCorp (External)	3.0	\$220/h	\$660	EXT-TR-Q2
TOTAL: 47.5h			\$5,998	

RELATED INCIDENTS & DOCUMENTS

INC-2025-1187 | Micro-bend Jan 2026 | Repair Report 2026-01-15 | CLOSED
INC-2026-0089 | Fiber break Mar 2026 | Repair Report 2026-03-01 | CLOSED
WO-2026-0287 | Conduit replace Phase 1 | Completed 2026-03-25 | CLOSED
WO-2026-0391 | Emergency re-assessment | In Progress | OPEN
CR-2026-04-10 | Full corridor condition | Condition Report | ACTIVE
FSE-2026-0041 | Splice engineering sheet | As-Built 2026-04-28 | CURRENT

ADDENDUM -- Webb 05/06:

Total reactive spend this corridor since Jan: \$74,200 (42 customers at risk)
Corridor rehab approved by VP Daniels (\$120K, BUD-2026-TR-009).
Replacement 05/19. Team A + GeoCorp. See FRD-2026-04-28.

REVIEW CHECKLIST:

- ☒ Field data verified
- ☒ Budget codes confirmed
- ☐ Escalation required

J. Alvarez
Lead Inspector
Date: 2026-05-06

P. Sharma
Senior Field Tech
Date: 2026-05-06

M. Webb
Operations Manager
Date: 2026-05-06



SCAN TO VERIFY

--- DOCUMENT CROSS-REFERENCE INDEX ---

PL-2026-04-10-TR9 Photo Log (Alvarez, 04/10)
VID-IDX-2026-04-10-TR9 Video Inspection (Alvarez, 04/10)
AUD-2026-04-15-TR9 Audio Transcript (Sharma/Alvarez, 04/15)
DOC-PHOTO-2026-05-02 Inspection Photos (Alvarez, 05/02)
FSE-2026-0041 Splice Engineering Sheet (Nakamura, 04/28)
FRD-2026-04-28 Fiber Routing Analysis (Nakamura, 04/28)
PLT-DC-TR-001-E Plant Diagram (Nakamura, 04/28)
PO-2026-0391 Equipment Order (Webb, 05/03)

Q1 RECURRING: INC-2025-1187 (Jan splice), INC-2026-0089 (Feb patch),
INC-2026-0287 (Mar barrier) -- all at Vault TV-3, Segment 9.
Route 2 shares conduit Sections 3-5: 34+8 = 42 customers, no redundancy.