

PHOTOGRAPHIC INSPECTION LOG

Zava Telecom -- Field Operations Division

Site B -- Segment 9 (Tower Ridge Corridor)
Inspector: J. Alvarez | Date: 2026-04-10 | Weather: Clear, 18C
Camera: Nikon D850 + 24-70mm f/2.8 | GPS: Enabled

PHOTO INDEX -- FULL CORRIDOR WALK

Photo#	Time	GPS	Subject	Priority	Ref Doc
IMG_001	08:15	34.0522,-118.2437	Pole TR-38 base -- erosion	HIGH	CR-04-10-S1
IMG_002	08:22	34.0523,-118.2435	Guy wire anchor plate	LOW	CR-04-10-S1
IMG_003	08:45	34.0525,-118.2430	Conduit route marker #1	MED	CR-04-10-S2
IMG_004	09:10	34.0528,-118.2425	Vault TV-1 exterior	LOW	CR-04-10-S3
IMG_005	09:30	34.0530,-118.2420	Surface crack above conduit	HIGH	CR-04-10-S3
IMG_006	10:00	34.0533,-118.2415	Vault TV-2 interior	MED	CR-04-10-S4
IMG_007	10:35	34.0536,-118.2410	Jersey barrier alignment	MED	CR-04-10-S5
IMG_008	11:00	34.0538,-118.2405	Vault TV-3 -- CRITICAL (recurring)	CRIT	CR-04-10-S5
IMG_009	11:15	34.0538,-118.2405	Conduit crack closeup (2cm, growing)	CRIT	CR-04-10-S5
IMG_010	11:30	34.0538,-118.2405	Fiber sleeve displaced (micro-bend)	CRIT	CR-04-10-S5
IMG_011	12:00	34.0540,-118.2400	Section 5 pavement heave	HIGH	CR-04-10-S6
IMG_012	12:30	34.0542,-118.2395	Splice enclosure SE-24F	LOW	CR-04-10-S7
IMG_013	13:00	34.0545,-118.2390	JB-9B junction box	MED	CR-04-10-S8
IMG_014	13:30	34.0548,-118.2385	End marker -- corridor end	LOW	CR-04-10-S9

Total images captured: 147 | Index shown: Critical + sample
Full set uploaded to: FS-ARCHIVE/TR-CORRIDOR/2026-04-10/

PRIORITY BREAKDOWN:

CRITICAL: 3 images (Vault TV-3 damage complex)
HIGH: 3 images (Erosion, surface crack, pavement heave)
MEDIUM: 4 images (Barriers, vaults, markers)
LOW: 4 images (Reference/baseline documentation)



J. Alvarez, Lead Inspector
Date: 2026-04-10

--- COMPANION DOCUMENTS ---
Video: VID-IDX-2026-04-10-TR9 (same walk, same day, J. Alvarez)
Audio follow-up: AUD-2026-04-15-TR9 (Sharma + Alvarez, 04/15)

--- RECURRING INCIDENT HISTORY (Vault TV-3) ---
INC-2025-1187 Jan 2026 Emergency splice (strand 11) CLOSED
INC-2026-0089 Feb 2026 Conduit patch (temporary) CLOSED
INC-2026-0287 Mar 2026 Barrier shift (3rd occurrence) OPEN
Crack progression: <1cm (Jan) -> 2cm (today) -> 3cm (04/15 audio)

CRITICAL: Route 2 shares conduit Sections 3-5 with Route 1.
34 + 8 = 42 customers at risk with no redundancy path.