


1	2	3	4	5	6	7	8
Notes The relay coils carry no flyback diode: they are small, and the PLC output module switches them.							
A							A
B							B
C							C
D							D
E							E
F							F
Title Relay interface board				Number SKX-RIB-2	Revision 1.3	Revision date 2026-10-05	
Customer	Author fransys-examples	Page title Notes		Scope Relay interface board	Sheet	Page 2 of 5	
1	2	3	4	5	6	7	8



1	2	3	4	5	6	7	8
Designation	Style	Pincount	Gender	Marking			
-J1	mstb-header-3p	3	female	1			
-J1	mstb-header-3p	3	female	2			
-J1	mstb-header-3p	3	female	3			
-J2	mstb-header-3p	3	female	1			
-J2	mstb-header-3p	3	female	2			
-J2	mstb-header-3p	3	female	3			

1	2	3	4	5	6	7	8
Mpn	Manufacturer	Description	Count	Designations			
1757255	Phoenix Contact	PCB header, 3-pin, 5.08 mm pitch	2	-J1; -J2			
40.61.9.024.1000	Finder	PCB relay, 1 changeover contact, 16 A, 24 V DC coil	2	-K1; -K2			
SKX-RIB-2	this repo	Relay interface board, 2 channels, revision 01	1				
Title Relay interface board			Number SKX-RIB-2		Revision 1.3	Revision date 2026-10-05	
Customer		Author fransys-examples	Page title BOM		Scope Relay interface board	Sheet	
1	2	3	4	5	6	7	8