

CYSH12AF (InSb) HALL-EFFECT ELEMENT


Hall-effect element CYSH12AF is made of compound semiconductor material indium stibnite (InSb), which utilizes the Hall-effect principle. It can convert a magnetic flux density signal linearly into voltage output. It is new generation of Hall Effect element CYTY101A.

FEATURES

- High Magnetic Sensitivity
- Low Offset Voltage
- Miniature Package

TYPICAL APPLICATION

- Magnetic Field Measurement
- Current Sensor
- Detection of Speed
- DC Brushless Motor
- Position Control



1. Maximum Ratings

(Ta=25°C)

| Parameter | Symbol | Rating | Unit |
|-----------------------------|--------|---------------|------|
| Maximum Input Current | Imax | 20 (at 25°C) | mA |
| Maximum Power Dissipation | Pmax | 150 (at 25°C) | mW |
| Operating Temperature Range | Тор | - 40 ~ + 110 | °C |
| Storage Temperature Range | Tst | - 40 ~ + 150 | °C |

2. Electrical Characteristics (Measured at 25°C)

| Parameter | Symbol | Measurement Conditions | Min | Max | Unit |
|---------------------------|--------|----------------------------------|-----|-------|-------|
| Output Hall Voltage | VH | Vin = 1V, B = 50mT | 196 | 415 | mV |
| Input Resistance | Rin | I = 0.1mA | 240 | 550 | Ω |
| Output Resistance | Rout | I = 0.1mA | 240 | 550 | Ω |
| Offset Voltage | VO | Vin = 1V, B = 0G | -7 | +7 | mV |
| Temp. Coeff. of VH | α | Ta = $0 \sim +40^{\circ}$ C AVG. | - | - 1.8 | % /°C |
| | | B=50mT, Ic=5mA | | | |
| Temp. Coeff. of Rin, Rout | β | Ta = $0 \sim +40^{\circ}$ C AVG. | - | - 1.8 | % /°C |
| | | B=0, lc=0.1mA | | | |

VH = VHM - VO (VHM: The output voltage measured at 500G.)

3. Rank Classification and Mark on Output Hall Voltage


| Output Hall Voltage,VH (mV) | Rank | Mark | Measurement Conditions |
|-----------------------------|------|------|-----------------------------------|
| 196 ~ 236 | D | SSD | |
| 228 ~ 274 | E** | SSE | Via 4V D 50mT |
| 266 ~ 320 | F** | SSF | Vin=1V, B=50mT (Constant Voltage) |
| 310 ~ 370 | G | SSG | (Constant Voltage) |
| 360 ~ 415 | Н | SSH | |


** Als standard sensor we offer our customers the rank E and F


Email: info@cy-sensors.com http://www.cy-sensors.com





4. CHARACTERISTIC CURVES (only for references)














5. Method for Mounting

5-1. Soldering Conditions on PCB


- 1. No Rapid Heating and Cooling.
- 2. Recommended Preheating condition is at 130~150°C for 2~3minutes.
- 3. Recommended Reflowing condition is at 220~230°C for 10~15seconds.

Email: info@cy-sensors.com http://www.cy-sensors.com



5-2. Soldering Method and Temperature


| Items | Methods | Temperature |
|-------------|--------------------------------------|--------------------|
| Reflow | Soldering by Passing the Heated Zone | Max 250°C in 20sec |
| Solder Iron | Soldering by Soldering Iron | Max 300°C in 3sec |



6. Packaging

6-1. Taping


- 1. CYSH12AF should be packed that marked side is viewed from cover tape andlong side is put parallel with tape running direction. Making use of itafter 180° rotation has no problem because of its symmetric mode.
- 2. The vacant parts more than 40mm are located at front and end side of the reel.



http://www.cy-sensors.com

6-2. Tape Specifications

1. Pull Strength(F) = 20~70g




- 2. Devices should not be flipped out of a pocket when tape is bent down by 15mm curvature.
- 3. Devices should not be stuck to cover tape.
- 4. Devices should be kept below 40°C and below RH80% in the shade.
- 5. Tape has no joint.

6-3. Packing Unit

- 1. 3,000pcs of devices are packed in one reel.
- 2. Five reels are packed in one inner box.
- 3. Four inner boxes, 60,000pcs of devices, are packed in one outer box.
 - 4. Dummy could be packed for safe dealing.


7. External Dimensions (Unit: mm)

Four leads of input and output terminals are designed in the diagonally symmetric mode and are equal in dimensions. Regardless of 180° rotation of Hall sensor, CYSH12AF can be used.





Connection



Application Notes

The Hall voltage V_H can be positive and negative. But if one connects the sensor as follows (circuit1):

Pin 1: positive input voltage V+, for instance +5VDC.

Pin 3: GND
Pin 2: OUTPUT
Pin 4: GND

One can only measure the positive voltage at the pin 2. This means that the output voltage at zero magnetic field is not zero. This voltage is called as offset voltage. The output voltage in this case is not equal to the Hall voltage. The output voltage is equal to the sum of offset voltage and Hall voltage.

The offset voltage will be zero if you connect double power supplies V+ and V- to the sensor (circuit 2):

Pin 1: positive input voltage V+, for instance +5VDC. Pin 3: negative input voltage V-, for instance -5VDC

Pin 2: OUTPUT Pin 4: GND

In this case the output voltage is equal to the Hall Voltage.



8. RELIABILITY

8. 1 TEST CONDITION

| | CONDITION |
|-----------------------------------|---|
| HIGH TEMP. STORAGE | Ta=110°C,t=1000HR |
| LOW TEMP. STORAGE | Ta=-40°C,t=1000HR |
| HIGH TEMP. OPERATION | Ta=100°C,lopr=6mA,t=1000HR |
| LOW TEMP. OPERATION | Ta=-20°C,lopr=6mA,t=1000HR |
| HIGH TEMP. HIGH UMIDITY OPERATION | Ta=60°C, HR=90%,lopr=9mA,t=1000HR |
| HUMIDITY | Ta=60°C,HR=90%, t=1000HR |
| PCT | Ta=121°C,HR=100%, Pv=2atm, t=24HR |
| THERMAL SHOCK | T(L)=-55°C,T(H)=150°C, t=(L,H)=30min,M=30CYCLE |
| SOLDERING HEAT | solder temp=250±5°C, t=10sec,REFLOW |
| RESISTANCE | |
| SOLDABILITY | solder temp=230±5°C, t=5sec,dip |
| TERMINAL STRENGTH | TENSION 300g/30sec |
| SURGE | V=500V, C=200pF, R=0Ω (test method EIAJ EDX 8503) |

8.2 CRITERION FOR JUDGING

After each reliability test, samples should be kept for at least 24 hrs at room temp. & humidity, and then measured.

The change rates should be confined within the ranges as follows.

| item | OK SPEC | NG/OK |
|--------|------------|----------------------|
| ΔRin | UNDER ±20% | |
| ΔRout | UNDER ±20% | OK (SPEC SATISFYING) |
| ΔVΗ | UNDER ±20% | |
| ΔVo/VH | UNDER ± 5% | |

Tel.: +49 (0)8121 - 2574100

Fax: +49 (0)8121- 2574101

Email: info@cy-sensors.com http://www.cy-sensors.com