LIMO Pothole Evaluation

```
{"idx": 0, "x": 0.925295230558007, "y": -0.06287756"
{"idx": 1, "x": 1.232682125336018, "y": 0.095442167
{"idx":
        2, "x": 1.2264391331791091, "y": -0.4787039
{"idx":
          "x": 0.73211489849373, "y": -1.0568727183
        3,
          "x": -0.008700996328757121, "y": -0.84049
{"idx":
        4,
          x'': -0.33818173897016934, y'': -1.003949
{"idx":
        5,
{"idx":
          "x": -0.13945143086347447, "y": -0.630986
        6,
{"idx":
          x'': -0.6421035491445902, y'': -1.0739646
        7,
{"idx":
           "x": -1.0553074423611746, "y": -0.9215179
        8,
{"idx":
        9, "x": -1.1708718266517026, "y": -0.842511
{"idx":
        10, "x": -1.2062654913207953, "y": -0.19586
{"idx":
        11, "x": -0.7913125743954195, "y": 0.1440150
{"idx": 12, "x": -0.6958453300732435, "y": -0.18541!
{"idx": 13, "x": -0.29154528908173666, "y": -0.1694"
{"idx": 14, "x": -0.11704420288819384, "y": 0.056800
{"idx": 15, "x": 0.1892867403732842, "y": -0.0049753
{"idx": 16, "x": 0.34344274191584023, "y": 0.054034"
```