File - main

```
C:\Users\leoan\Documents\Cybersecurity-Portfolio\PythonProjects\Drone-telemetry\.venv\Scripts\python.exe C:\Users\leoan\Documents\Cybersecurity-Portfolio\PythonProjects\Drone-telemetry\main.py
t=  2.0s reached (0, 0, 10) pos=(0.0, 0.0, 10.0)
t= 12.0s reached (50, 0, 10) pos=(50.0, 0.0, 10.0)
t= 22.0s reached (50, 50, 10) pos=(50.0, 50.0, 10.0)
t= 32.0s reached (0, 50, 10) pos=(0.0, 50.0, 10.0)
t= 42.0s reached (0, 0, 10) pos=(0.0, 0.0, 10.0)
Flight complete.
Saved 42 GPS readings to telemetry_clean.csv
Saved 420 IMU readings to imu_clean.csv
t=  2.0s reached (0, 0, 10) pos=(0.0, 0.0, 10.0)
t= 12.0s reached (50, 0, 10) pos=(50.0, 0.0, 10.0)
t= 22.0s reached (50, 50, 10) pos=(50.0, 50.0, 10.0)
t= 32.0s reached (0, 50, 10) pos=(0.0, 50.0, 10.0)
t= 42.0s reached (0, 0, 10) pos=(0.0, 0.0, 10.0)
Flight complete.
Saved 42 GPS readings to telemetry_faulty.csv
Saved 420 IMU readings to imu_clean.csv

Process finished with exit code 0

```