Certificate of Authorization

ISI

Has received training and is authorized* to inspect and repair

David Gerena

3400900/901/902 Series Blocks, 3400920/921/922/923/924 Series blocks, 3400930 RSQ Block, 3103020 Series Blocks, 3506000 Series Blocks, 7605060 EZ-Line, UCL Digital Winch Series, 3400610/611/612 Series Blocks, 3504550 Ultra-Lok RSQ Series 3590500/510/501/511 Series 3590630/640/631/641 Series Blocks, 3590670/680/671/681 Series Blocks, 3303000/3303015 3101000/3101050 Series Blocks, 3102000 Series Blocks, 3103107/3103207 Series Blocks, Rollgliss Descent Devices, 8102000 Sala II Winches, 3000057/3000150 Series Blocks, 3400825/826/827 Series Blocks, 3400800/801/802/850/851/852/853 Series Blocks, Blocks, 3590550/560/551/561 Series Blocks 3590590/600/591/601 Series Blocks, AD215AG Block, AD120A Series blocks, AD115B Series Blocks

In accordance with specified procedures.

*Certificate holder is not authorized to train others on inspecting and repairing DBI/SALA Protecta product.

*Certificate holder is authorized to inspect and repair DBI/SALA Protecta product while employed at the company listed above.

Comothy a. Wiss

DBI/SALA Protecta Representative

March, 2011