



ROWAD
MODERN ENGINEERING

Control of Measuring Devices Process
P-QD-03

Prepared by:

Sameh Herazy

Quality Control Dept Mgr.

Reviewed by:

Mohamed Ragab

COO

Approved by:

Mohamed Mahlab

CEO

Nov, 2021

	Control of Measuring Devices Process		
	Effective Date: Nov, 2021	Rev. No.: 01	Doc. No.: P-QD-03

1.OBJECTIVES

The objective of this process is to ensure that measuring and testing equipment, tools and devices affecting the quality of the services are suitably identified, calibrated, controlled, and maintained.

2. STAKEHOLDER

- Construction
- QC
- Subcontractor

3. LIABLE STAKEHOLDER

- Construction
- QC
- Subcontractor
- Staff supervisor

4. TERMS AND DEFINITION

- QC: Quality Control
- HoD: Head of Department

5. RELATED DOCUMENTED INFORMATION

- Measuring Equipment Calibration Log, F-P-QD-03-01

6. PROCESS DETAILS

6.1 PROCESS INPUT

- Specification Requirements
- Manufacture Recommendations

	Control of Measuring Devices Process		
	Effective Date: Nov, 2021	Rev. No.: 01	Doc. No.: P-QD-03

6.2 Process Operations

Sr.	Process Cycle description	Responsibility	Form
1	Measuring Devices under RME Properties Staff supervisor shall maintain the calibration of equipment and QC shall update the equipment logs (i.e., Survey Levels, Total Stations, etc.) to include: - Calibration Plan - Identification of equipment's expired calibration	Supervisor QC	Calibration Log F-P-QD-03-01
2	QC shall inform the entitled supervisor with the required calibration and maintain quality calibration records.	QC	
3	QC shall inform the entitled supervisor with the maintenance date according to the preventive maintenance plan for the concerned equipment.	QC	
4	Doubtful measuring equipment shall be tested regarding accuracy and suitability for usage vs calibrated equipment. For example, comparing the concerned equipment with accurate or new equipment, no record required.	Supervisor	
5	Measuring Equipment under the Contractor's/Supplier's Possession Prior to using such equipment, QC shall request calibration/conformance certificates from the organization using such equipment/devices to ensure valid calibration.	QC	Calibration Certificates

6.3 PROCESS OUTPUT

- Calibration Certificate
- Calibrated Equipment

	Control of Measuring Devices Process		
	Effective Date: Nov, 2021	Rev. No.: 01	Doc. No.: P-QD-03

7. PROCESS RISK ASSESMENT

- Included in the risk register form no. F-P-QD-05-01 “Risk identification and assessment” maintained by the HoD, along with the action plan to address risks and opportunities”.

8. PROCESS CONTROL

- QC shall monitor the calibration due dates through Calibration Log.

9. PERFORMANCE MEASURES

QC shall measure the performance of this procedure/process through:

- Cases of non-conformity or threats resulting from the use of un-calibrated equipment.
- Execution of calibration plans.
- Wasted time or man-hours resulting from out-of-order facility or equipment.

10. DOCUMENT CHANGE HISTORY

No.	Revision Level	Description of Changes	Effective Date
01	00	Major Changes due to transition from ISO 9001:2008 to 9001:2015	01/12/2016
02	01	All Points	28/11/2021