



+



upper
Joint



Middle
Joint



Lower
Joint




Base

E0


Z

Y


X




SD3, SDE4
SCL3, SCL4
SD0+SD1
SCL0+SCL1




4




3




2




1




any Ground
Vin Gnd
any gnd + -




+ VCC
GND





USE 15V at your own risk. if not use 12V But never use 20V as intended



Camera sensor




TXD RXD RXD TXD




SD4 SD SC4 SC


Arm sensor



GND + VIN



Bridge these 2 pins



Camera tilt

Camera pan

Hand servo

