

BCM Door Functionality Validation Report

Test Execution Summary

Total Test Cases : 11


Passed Test Cases : 5

Failed Test Cases : 6

Pass Percentage : 45.45%

Fail Percentage : 54.55%

Pass / Fail Pie Chart



Detailed Test Results

TC_ID	Description	Expected	Actual	Status	Remarks
TC01	Lock door using key fob	Door Locked	Door Unlocked	Fail	Driver Door Open, Rear Left Door Open, Boot Door Open, Lock Failed
TC02	Unlock door	Door	Door	Pass	Driver Door

	using key fob	Unlocked	Unlocked		Open, Unlock Successful
TC03	Verify unlock is allowed at low speed value<10	Door Locked	Door Unlocked	Fail	Unlock Allowed
TC04	Verify unlock is blocked above speed limit>10	Door Unlocked	Door Unlocked	Pass	Rear Right Door Open, Unlock Allowed
TC05	Verify unlock at boundary value 60 km/h	Door Locked	Door Unlocked	Fail	Driver Door Open, Rear Left Door Open, Unlock Allowed
TC06	Verify auto-lock activates above 20 km/h	Door Locked	Door Locked	Pass	Auto Lock Activated
TC07	Verify auto-lock does not activate below threshold(20)	Door Unlocked	Door Unlocked	Pass	Rear Right Door Open, Speed Below Auto Lock Threshold
TC08	Verify lock command when driver door is open	Door Locked	Door Unlocked	Fail	Driver Door Open, Lock Failed
TC09	Verify central lock request	Door Locked	Door Unlocked	Fail	Rear Right Door Open, Central Lock Failed
TC10	Verify central unlock request	Door Unlocked	Door Unlocked	Pass	Unlock Allowed
TC11	Verify lock request when boot door open	Door Locked	Door Unlocked	Fail	Boot Door Open, Lock Failed

Failed Test Cases

TC01 : Driver Door Open, Rear Left Door Open, Boot Door Open, Lock Failed

TC03 : Unlock Allowed

TC05 : Driver Door Open, Rear Left Door Open, Unlock Allowed

TC08 : Driver Door Open, Lock Failed

TC09 : Rear Right Door Open, Central Lock Failed

TC11 : Boot Door Open, Lock Failed

Conclusion

A total of 11 test cases were executed.

5 test cases passed.

6 test cases failed.

Pass Percentage : 45.45%