

Detection

CFAR Method	CFAR-C...
CFAR Guard Window	8
CFAR Window Size	32
CFAR Threshold (dB)	18

Interference mitigation

Mitigation Method	Do not pe...
Interference Thresh	-53
Window	Rectangu...

Miscellaneous

Separate real/i	Show co...
Image band options	show im...
DC removal	Do not re...
Detection Over	Do not ov...

Data Munging

Remove samples?	Do not re...
num_samples_to_drop	0
Hold previous plot	Clearplot...

FFT processing Settings

Non-Coherent Interference	No non-c...
Oversampling ratio	1
x axis selection	Range/V...
FFT Window	HannWin...

Time-domain Plotting

Time domain v-axis	ADC cod...
Time domain x-axis	Time(se...
Time domain	Do not all...
Auto-scale options	auto-scal...

More Miscellaneous

Gain Compensation	Perform ...
Chirp Picture options	ChirpCo...
Number of plots	4
Multi-profile Process	Chirp con...

Record and Playback

movie file to read	
offset (seconds)	0
movie file to save as	
Record a movie?	Do not re...