

AUTO CLAIMS DIRECT

3196 WILLOW CREEK RD
PRESCOTT, AZ 86301
Phone: (602) 773-1961

Workfile ID:

1449b80e

For:

AUTO CLAIMS DIRECT

NATIONWIDE GENERAL INS.

Preliminary Estimate**Owner: BRAYBOY, STACY****Job Number:**

Written By: Vernon Long
Adjuster: Boone, Brittany, (833) 369-2567 Business

Insured: BRAYBOY, STACY
Type of Loss: Collision
Point of Impact: 09 Left T-Bone (Left Side)

Policy #:
Date of Loss: 10/1/2025 12:00 PM

Claim #: 754114-GQ-2
Days to Repair: 11

Owner:
BRAYBOY, STACY
620 CANAL RD
Pembroke, NC 28372
(910) 827-1701 Cell
(910) 521-9542 Business

Inspection Location:
Deese Body Shop
2041 UNIVERSITY RD
Pembroke, NC 28372
Other
(910) 522-1332 Day

Repair Facility:
Deese Body Shop
2041 UNIVERSITY RD
Pembroke, NC 28372
(910) 522-1332 Business

VEHICLE

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

VIN: 5J6RW1H80NA011968
License: TPV5227
State: NC

Production Date: 2/2022
Odometer: 63,350
Condition: Good

Interior Color:
Exterior Color: SILVER

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

Dual Mirrors
Privacy Glass
Console/Storage

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Backup Camera
Remote Starter
Intelligent Cruise

FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection
Satellite Radio
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

Electric Glass Sunroof

SEATS

Bucket Seats
Leather Seats
Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Rear Spoiler
Signal Integrated Mirrors

TRUCK

Power Trunk/Liftgate

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

Overhead Console

Home Link

Blind Spot Detection

Wood Interior Trim

RADIO

Lane Departure Warning

CONVENIENCE

AM Radio

ROOF

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE					
2	R&I	R&I bumper cover as an assy				1.4	
		Note: LABOR: Time include R&I grille assembly, R&I/R&R lower cover, lower deflector, molding, sight shield and trim bezels. Time is after wheel opening moldings are removed.					
3	R&I	LT Upper molding				0.2	
4		FRONT LAMPS					
5	R&I	LT R&I headlamp assy				0.3	
6		FENDER					
7	*	Rpr <u>LT Fender BEND</u>				<u>1.0</u>	<u>0.0</u>
8	*	Blnd <u>LT Fender</u>					<u>0.9</u>
9	R&I	LT Fender liner w/o hybrid				0.4	
10	R&I	RT Wheel opng mldg all				0.3	
11	R&I	LT Wheel opng mldg all				0.3	
12		RESTRAINT SYSTEMS					
13	Repl	Diagnostic unit w/o hybrid	77960TLAA42	1	488.88 m	0.6	
14	Repl	LT Head air bag w/sunroof	78875TLAA62	1	1,395.32 m	0.6	
		Note: LABOR: Time is after headliner is removed.					
15	Repl	LT Ft seat air bag US built	78055TLAA92	1	501.62 m	0.3	
		Note: LABOR: Time is after front seat back cover is removed.					
16		Air bag system diagnosis			m	0.5	
17	Repl	LT Side impact sens front	77970TLAA01	1	42.42 m	0.2	
18	Repl	LT Belt & retractor all gray	04818TLAA00ZC	1	396.95 m	0.3	
19	Repl	LT Buckle EX, EX-L, Touring gray	04816TLAA30ZC	1	125.03	0.3	
20		SEATS & TRACKS					
21	R&I	LT R&I front seat				0.5	
22	Repl	Seat back pad w/leather	81527TNCA51	1	214.62	0.1	
23	Repl	Seat back cover w/leather gray	81525TLAA51ZC	1	900.95	1.0	
24		ROOF					
25	R&I	R&I headliner				5.7	
26		PILLARS, ROCKER & FLOOR					
27	Sect	LT Aperture panel cntr plr & rocker	04645TLAA00ZZ	1	1,229.13	13.5	2.5
28		Add for Clear Coat					1.0
29	R&I	LT W/S pillar trim gray				Incl.	
30	R&I	LT Cowl trim				0.2	
31	R&I	LT W'strip on body front				Incl.	
32	R&I	LT W'strip on body rear				Incl.	
33	R&I	LT Front sill plate				Incl.	
34	R&I	LT Rear sill plate				Incl.	
35	R&I	LT Lwr ctr plr trim				Incl.	
36	R&I	LT Up'r ctr plr trim gray				Incl.	
37		FRONT DOOR					
38	*	Repl RCY LT door assy +25%	67050TLAA10ZZ	1	<u>1,890.00</u>	<u>3.0</u>	<u>0.0</u>

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

Note: R. Stroud's, Inc. - PRP Freight, iPart, CDC USA-NC(Youngsville) Request_Quote 919-989-4836
QUOTE#N304466
DOOR IS ALREADY THE SAME COLOR W/ SAME MOLDINGS. NO NEED TO PAINTADDTL TIME GIVEN TO BUFF
DOOR. ONLY NEEDS PINSTRIPES

39		Repl	LT Applique	72470TLAA01	1	18.03	0.2	
			Note: PARTS: Part cannot be reused/reinstalled.					
40		R&I	LT Upper hinge				0.3	
41		R&I	LT Lower hinge				0.3	
42		R&I	LT Door check				0.2	
43		REAR DOOR						
44		Repl	LT Outer panel	67651TLAA00ZZ	1	343.03	6.0	2.0
45			Overlap Major Adj. Panel					-0.4
46			Add for Clear Coat					0.3
47			Add for Edging					0.5
48		R&I	LT Door w/strip all				Incl.	
49		R&I	LT Water deflector all				Incl.	
50		R&I	LT Belt molding all				Incl.	
51	**	Repl	A/M LT Lower molding w/o chrome	75333TLCA01	1	79.00	Incl.	
52		Repl	LT Upper molding	72965TLAA01	1	86.90	0.3	
			Note: PARTS: Part cannot be reused/reinstalled.					
53		R&I	LT Wheel opng mldg				0.2	
54		R&I	LT Rear applique				0.2	
55		Repl	LT Front applique	72970TLAA01	1	18.03	0.2	
			Note: PARTS: Part cannot be reused/reinstalled.					
56		R&I	LT Door glass Honda w/o privacy				0.3	
57		R&I	LT Run w/strip all				0.3	
58		R&I	LT Window regulator				0.4	
59		R&I	LT Handle, outside w/body color crystal black				Incl.	
60		R&I	LT R&I trim panel				Incl.	
61		QUARTER PANEL						
62	*	Blnd	LT Quarter panel 18" or 19" wheels					<u>1.2</u>
63		Repl	LT Protector	74452TMET01	1	44.98	0.2	
64		R&I	LT Wheel opng mldg all				0.3	
			Note: LABOR: Time for R&I does not include removing or replacing double-sided tape.					
65	#		CLEAN AND RETAPE		1	5.00	0.5	
66		Repl	LT Seal	73860TLAA01	1	14.30	0.2	
67		R&I	LT Quarter glass Honda w/o privacy				1.5	
			Note: PARTS: Part has related component that cannot be reused/reinstalled; seal. LABOR: Time is after upper and lower quarter trim panels are removed.					
68		R&I	LT Upper qtr trim w/o tonneau cover gray				Incl.	
69		REAR BODY & FLOOR						
70		R&I	LT Side trim panel w/o woofer				0.6	

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

71	VEHICLE DIAGNOSTICS				
72	*	Rpr	Pre-repair scan	m	0.5 M
73	*	Rpr	Post-repair scan	m	0.5 M
74	#	Subl	Hazardous waste removal	1	5.00
75	#	Subl	Cover Car	1	5.00
76	#	Rpr	Mask jams/openings		0.3
77	#	Rpr	Color tint / color match		0.5
78	**	Repl	A/M Seam sealer/caulking	1	25.00
79	**	Repl	A/M Urethane kit	1	15.00
80	#	Rpr	Disconnect battery cable		0.3
81	**	Repl	A/M Stripe - tape	1	15.00
SUBTOTALS				7,859.19	46.2
					8.0

NOTES

Prior Damage Notes:
NO UPD VISIBLE

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				7,859.19
Body Labor	45.2 hrs	@	\$ 55.00 /hr	2,486.00
Paint Labor	8.0 hrs	@	\$ 55.00 /hr	440.00
Mechanical Labor	1.0 hrs	@	\$ 95.00 /hr	95.00
Paint Supplies	8.0 hrs	@	\$ 44.00 /hr	352.00
Subtotal				11,232.19
Sales Tax	\$ 11,232.19	@	7.0000 %	786.25
Total Cost of Repairs				12,018.44
Deductible				250.00
Total Adjustments				250.00
Net Cost of Repairs				11,768.44

Supplements: <http://acdcorp.com/supp>

*THIS IS NOT AN AUTHORIZATION TO REPAIR OR ACCEPTANCE OF LIABILITY

*THIS IS NOT A FINAL APPROVED ESTIMATE, NOR ACCEPTANCE TO PAY

*SHOP TO PROVIDE AUTHORIZATION TO REPAIR/DIRECTION TO PAY FROM OWNER

*ESTIMATE PREPARED BY: E. Kolkhorst

*NO SUPPLEMENTS WITHOUT PRIOR AUTHORIZATION: ALL SUPPLEMENTS,
CALL FOR SUPPLEMENT REQUEST LISTED NUMBER PAGE 1 ORIGINAL ESTIMATE

*REQUIREMENT FOR ALL SUPPLEMENT REQUESTS: INVOICES, OLD PARTS, PHOTOS
HIDDEN /ADDITIONAL DAMAGE; MUST BE DOCUMENTED BY JPG PHOTOGRAPH

*TEAR DOWN PRIOR TO REPAIRS COMMENCING OR PARTS ORDERED

W/WRITTEN OWNER AUTHORIZATION

*AGREED PRICE (N) ESTIMATE TO SHOP (N)

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

*ESTIMATE MAILED TO THE OWNER (N)

*TOTAL LOSS (N) CCC REQUEST #

*RECYCLED PARTS USED (N)

*AFTERMARKET PARTS USED (Y)

THIS IS NOT AN AUTHORIZATION TO REPAIR. THIS IS AN APPRAISAL OF DAMAGES ONLY. NO APPRAISER HAS THE AUTHORITY TO AUTHORIZE REPAIRS. AUTHORIZATION AND GUARANTEE OF PAYMENT CAN ONLY BE GIVEN BY THE OWNER OF THE VEHICLE. ACD (AUTOCLAIMS DIRECT) AND ITS CLIENTS ASSUME NO RESPONSIBILITY FOR REPAIR QUALITY AND SAFETY. ACD (AUTOCLAIMS DIRECT) SPECIFIES AND INTENDS THAT ALL REPAIRS AND PART REPLACEMENTS LISTED HEREON ARE MADE IN STRICT ACCORDANCE WITH THE MANUFACTURER'S RECOMMENDATIONS AND SPECIFICATIONS. SUPPLEMENTAL DAMAGE IS SUBJECT TO REINSPECTION. FOR YOUR PROTECTION.

NOTE: YOU HAVE THE RIGHT TO SELECT THE BODY SHOP THAT WILL REPAIR YOUR VEHICLE.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE MADE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUIVALENT IN TERMS OF FIT, QUALITY, PERFORMANCE, AND WARRANTY TO THE ORIGINAL MANUFACTURER PARTS THEY ARE REPLACING.

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARG4464, CCC Data Date 10/01/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Bld=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
51	Partwerx Automotive Garner 1035 N GREENFIELD PARKWAY GARNER NC 27529 (980) 288-8600	#HO1504110 A/M LT Lower molding w/o chrome	\$ 79.00

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

ALTERNATE PARTS USAGE

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

VIN: 5J6RW1H80NA011968

Production Date: 2/2022

Interior Color:

License: TPV5227

Odometer: 63,350

Exterior Color: SILVER

State: NC

Condition: Good

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	2	4
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	1	1

Preliminary Estimate

Owner: BRAYBOY, STACY

Job Number:

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

RECALL INFO

2022 HOND CR-V EX-L 4D UTV 4-1.5L Turbocharged Gasoline Gasoline Direct Injection SILVER

VIN:	5J6RW1H80NA011968	Production Date:	2/2022	Interior Color:	
License:	TPV5227	Odometer:	63,350	Exterior Color:	SILVER
State:	NC	Condition:	Good		

The National Highway Transportation and Safety Administration (NHTSA) has issued 2 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 23V858000 **Issued: Dec 12, 23** **Number of Vehicles: 02490460**

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP Honda (American Honda Motor Co.) is recalling certain 2013-2023 Honda Accord, Civic Coupe, Civic Sedan, Civic Hatchback, Civic Type R, CR-V, HR-V, Ridgeline, Odyssey, Acura ILX, MDX, MDX Hybrid, RDX, RLX, TLX, 2019-2022 Honda Insight, Passport, 2020 Honda CR-V Hybrid, 2018-2019 Honda Clarity PHEV, Fit, and 2015-2020 Honda Accord Hybrid, Pilot, Acura NSX vehicles. The fuel pump inside the fuel tank may fail. Fuel pump failure can cause an engine stall while driving, increasing the risk of a crash. Dealers will replace the fuel pump module, free of charge. Owner letters were mailed September 6, 2024. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are KGC and KGD. This recall is an expansion of NHTSA recall numbers 21V-215 and 20V-314.

NHTSA ID: 23V524000 **Issued: Jul 7, 23** **Number of Vehicles: 00000005**

EQUIPMENT:OTHER:LABELS Honda (American Honda Motor Co.) is recalling certain 2017, 2020, and 2022 CR-V vehicles. The certification label on the driver's side door states incorrect Gross Vehicle Weight Rating (GVWR), Gross Axle Weight Rating (GAWR), and tire size information. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 110, "Tire Selection and Rims." An incorrectly sized tire may cause premature tread wear, or a tire blow out, increasing the risk of a crash. Dealers will install a new corrected label, free of charge. Owner notification letters were mailed September 18, 2023. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is CF7.