Issued date: 2026-10-07

Product Change Notification

Dear Customer, we want to inform you about the following changes.

If you have any questions regarding this issue, don't hesitate to contact your salesperson or our customer service team. We're happy to help you.

Type of change:

☒ Product ☐ Process ☐ Specification ☐ End-of-life ☐ Other

Affected item(s):

S12 CO2 sensor. Article number: 012-0-0001

Suggested replacement product(s):

N/A

Reason for change:

1. The function of Pin 6 (DE, communication Direction pin Enable) has been changed. The DE has been replaced to an EEPA (EEPROM Access). The EEPA output provides you with the EEPROM status when a write operation is in progress.

   This improves integration robustness by allowing the host system to monitor EEPROM activity and prevent interruptions during write cycles. As a result, users can identify appropriate timing for sensor power-down events or additional EEPROM or RAM writes.

2. The solder pad layout has been increased by 0.7mm (from 0.8mm to 1.5mm).

   This change is made in compliance with IPC requirements and greatly improves production capacity, solder joint reliability and mechanical robustness.

Expected influence on performance:

There is No impact on the sensor performance.

Qualification, Validation plan and Results:


Tested and verified in the project. Reference: CFR-P597-003

senseair.com
info@senseair.com
+46 653 71 77 70

Identification of changed item:


Updates are marked in blue in the drawings below.
The soldering pads are visibly larger.
Product specification (PSP15871) and S12 CO2 Reflow soldering instructions (TDE16239) will be updated accordingly.

Current drawings.



senseair.com
info@senseair.com
+46 653 71 77 70

New updated drawing.



Implementation date for change:	**Last ordering date:**
Q2-2027	N/A

senseair.com
info@senseair.com
+46 653 71 77 70