
Command Reference: WriteBlaneyCriddleToList()

Write Blaney-Criddle crop coefficients data to a delimited file

StateCU Command

Version 3.08.02, 2010-01-07

The WriteBlaneyCriddleToList() command writes Blaney-Criddle crop coefficients data to a delimited file. The following dialog is used to edit the command and illustrates the syntax of the command.



WriteBlaneyCriddleToList() Command Editor

WriteBlaneyCriddleToList

The command syntax is as follows:

WriteBlaneyCriddleToList(Parameter=Value,...)

Command Parameters

Parameter	Description	Default
OutputFile	The name of the output file to write,	None – must be specified.
	surrounded by double quotes.	
WriteHow	OverwriteFile if the file should be	OverwriteFile
	overwritten or UpdateFile if the file	
	should be updated, resulting in the	
	previous header being carried forward.	
Delimiter	The delimiter character to use between	Comma
	columns.	

The following example illustrates how to process crop characteristics data from HydroBase:

ReadBlaneyCriddleFromHydroBase(BlaneyCriddleMethod="BLANEY-CRIDDLE_TR-21")
WriteBlaneyCriddleToList(OutputFile="test.lst")