Command Reference: Exit()


Stop processing commands

Version 08.16.04, 2008-09-25

The Exit() command can be inserted anywhere in a command file and causes the processing of commands to stop at that line. This is useful for temporarily processing a subset of a long list of commands. Multi-line comments (/* */) can also be used to temporarily disable one or more commands. It may also useful to add an Exit() command at the end of the file so that it is easy to insert commands above this command when the end line is selected (rather than having to deselect all commands when editing).

In the future the command may be enhanced to have parameters that more explicitly control processing shut-down.

The following dialog is used to edit the command and illustrates the command syntax:



Exit() Command Editor

Exit

The command syntax is as follows:

Exit(Parameter=Value,...)

Command Parameters

Parameter	Description	Default
	There are currently no command parameters.	

A sample command file is as follows:

Exit()

Exit() Command **TSTool Documentation** This page is intentionally blank.