




$\{hkl\}\langle uvw \rangle$

Cube: $\{001\}\langle 100 \rangle$

Brass: $\{110\}\langle 1\bar{1}2 \rangle$

ODF

Goss: $\{110\}\langle 001 \rangle$

ODF

Cube: $\{001\}\langle 100 \rangle$

$f(g)$

Goss: $\{110\}\langle 001 \rangle$