Start

Preflight	
Flu	ids
Magnetos	OFF
Fuel quantity	CHECK VISUALLY
Fuel sumps	DRAIN
Left wing, right	wing, fuel strainer.
Inspect for con	
Fuel filler caps	SECURE
Engine oil level	CHECK
	Minimum 6 quarts
Cal	oin
Pitot cover	REMOVE
POH	VERIFY PRESENT
Master	ON
Flaps	EXTEND
Fuel gauges	CHECK QUANTITY
Lights	CHECK
Tach time	RECORD
Pitot heat	TEST
Master	OFF
Fire extinguisher	SECURE
Control lock	REMOVE
Emper	
Rudder gust lock	REMOVE
Control surfaces	CHECK
	ement and security
Rig	·
Main wheel tire	CHECK INFLATION
Aileron	CHECK
	ement and security
No	
Propeller, spinner	CHECK
	r nicks and security
Landing light	CHECK CLEAR
Air filter	CHECK CLEAR
Nosewheel & strut	CHECK INFLATED
Static source	CHECK CLEAR
Le	
Main wheel tire	CHECK INFLATION

Preflight (continued)	
Fuel tank vent	CHECK CLEAR	
Pitot tube	CHECK CLEAR	
Stall warning	TEST	
Aileron	CHECK	
Freedom of movement and security		
Final		
Flight Circle	DISPATCH	
Tach, Hobbs times	RECORD	
Baggage door	LOCK	
Chocks	REMOVE	
Tie-downs	REMOVE	

Securing	
Control lock	INSTALL
Tie-downs, chocks	APPLY
Vents, windows	CLOSE
Pitot cover	APPLY
Tach, Hobbs times	RECORD
Flight Circle	CHECK IN
Doors	LOCK
-	

Speeds		
		KIAS
Best glide (V _G)		65
Best angle of climb (V _x)	Sea level 10,000 ft	64 62
Best rate of climb (V _Y)	Sea level 10,000 ft	78 68
Landing approach	Flaps up Flaps 40	60-70 55-65
Normal takeoff climb		70-80
Short-field takeoff climb	Flaps up Flaps 10	59 55
Normal enroute climb	Sea level 10,000 ft	80-90 70-80
Design maneuvering speed (V _A)	2300 lbs 1950 lbs 1600 lbs	97 89 80

Light Gun Signals Aircraft on the Ground Aircraft in Flight Cleared to land Cleared for takeoff Return for landing (to be followed Cleared for taxi by steady green at the proper time) Give way to other aircraft and continue circling STOP I Taxi clear of the runway in use Airport unsafe, do not land Return to starting point on airport \square \square Not applicable Exercise extreme caution Exercise extreme caution

Operating Checklists

Before Start		
Preflight inspection	COMPLETE	
Passenger briefing	COMPLETE	
Brakes TE	ST and SET	
Seats, belts, harnesses	SECURE	
Fuel valve	BOTH	
Radios, electrical equipment	OFF	
Circuit breakers	CHECK IN	
Beacon switch	ON	
Engine Start		
Mixture	RICH	
Carburetor heat	COLD	
Prime AS	REQUIRED	
Throttle OPE	N 1/8 INCH	
Master	ON	
Propeller area	CLEAR	
Ignition switch	START	
Release when er	3	
Oil pressure	CHECK	
If no pressure in 30 seconds	•	
Mixture GRC	DUND LEAN	
Before Taxi		
Avionics	ON	
Headset	ON	
Flaps	RETRACT	
	VERIFY ALT	
Weather	OBTAIN	
Altimeter	SET	
	AS DESIRED	
Navigation, landing lights	ON	

Run-up	
Instruments	CHECK and SET
VOR check	IF NEEDED
Brakes	SET
Doors and windows	CLOSED, LOCKED
Flight controls	FREE and CORRECT
Fuel valve	BOTH
Mixture RI	CH (below 3000 feet)
Throttle	1700 RPM
Magnetos	CHECK
Max drop 125 R	PM, max diff. 50 RPM
Engine gauges, amn	neter CHECK
Vacuum gauge	CHECK
Gyroscopic instrume	nts CHECK
Carburetor heat	TEST
Idle	TEST
Mixture	GROUND LEAN
Throttle friction	ADJUST

Before Takeoff		
Radios, navigation	n, instruments	SETUP
Takeoff briefing	CC	MPLETE
Beacon, navigatio	n, landing lights	o ON
Carburetor heat	AS RE	QUIRED
Flaps		0-10°
Trim	7	AKEOFF
Fuel valve		BOTH
Fuel quantity		CHECK
Mixture	RICH (below 30	00 feet)

Climb	
Airspeed	70-90 KIAS
Throttle	FULL
Mixture	RICH (lean above 3000 feet)

Cruise	
Power	2200-2700 RPM (≤75%)
Trim	ADJUST
Mixture	LEAN (for max RPM)

Descent	
Mixture	RICH
Power	AS DESIRED
Carburetor heat	AS REQUIRED

Before Landin	ig `
Fuel valve	ВОТН
Mixture	RICH
Carburetor heat	ON
Airspeed	60-70 KIAS (flaps UP)
Flaps	AS DESIRED
Airspeed	55-65 KIAS (flaps DOWN)

Balked Landing	
Throttle	FULL
Carburetor heat	COLD
Flaps	20°
Airspeed	55 KIAS
Flaps	RETRACT slowly

After Landing	· ·
Flaps	UP
Caburetor heat	OFF
Mixture	GROUND LEAN

Shutdown	
Brakes	SET
Tach time	RECORD
Radios, electrical equipment	OFF
Mixture	CUT-OFF
Magnetos	OFF
Master	OFF

Version 1 PR 58

Engine Failures, Forced Landings

OFF

Engine Failure During Takeoff Run	
Throttle	IDLE
Brakes	APPLY
Flaps Mixture	RETRACT
Mixture	CUT-OFF
Magnetos	OFF

Engine Failure Shortly After Takeoff Airspeed Flaps up: 65 KIAS Flaps down: 60 KIAS Mixture CUT-OFF Fuel valve OFF Magnetos OFF Flaps AS REQUIRED

Master

Engine Failure During Flight Airspeed 65 KIAS Carburetor heat ON Fuel valve BOTH Mixture RICH Magnetos BOTH (START if prop stopped) Primer IN and LOCKED

Forced Landing	With Engine Failure
Airspeed	Flaps up: 65 KIAS
	Flaps down: 60 KIAS
Mixture	CUT-OFF
Fuel valve	OFF
Magnetos	OFF
Flaps	AS REQUIRED
	40° recommended
Master	OFF
Doors UNLATCH	BEFORE TOUCHDOWN
Touchdown	SLIGHTLY TAIL LOW
Brakes	APPLY HEAVILY

Precautionary Landing	
Flaps	20°
Airspeed	60 KIAS
Selected field	FLY OVER
Note terrain/obstructions.	
Retract flaps upon reaching	
a safe altitude and airspeed.	
Radios, electrical	switches OFF
Flaps	40° (on final approach)
Airspeed	60 KIAS
Master	OFF
Doors UNLATCH	H BEFORE TOUCHDOWN
Touchdown	SLIGHTLY TAIL LOW
Magnetos	OFF
Brakes	APPLY HEAVILY

Ditching	
Radio	MAYDAY on 121.5 MHz
	Give location, intentions
Heavy objects	SECURE or JETTISON
Flaps	20°-40°
Power 300 FT	/MIN DESCENT AT 55 KIAS
If no power	r available, approach
flaps up 65	KIAS or flaps 10° 60 KIAS
Strong wind, h	eavy seas:
LAND INTO \	WIND
Light wind, he	avy swells:
LAND PARAL	LEL TO SWELLS
Doors	UNLATCH
Touchdown	LEVEL ATTITUDE
at e	stablished rate of descent
Face CUSHIC	ON at touchdown with coat
Airplane	EVACUATE
Life vests/raft	INFLATE

Fires, Icing, Flat Tire, Electrical

Wing Fire

Cranking		CONTINUE
If engine starts		
Power	1700 RPM fo	r a few minutes
Engine		SHUTDOWN
If engine fails to	start:	
Throttle		FULL OPEN
Mixture		CUT-OFF
Cranking	CONTINUE	for 2-3 minutes
Fire extinguis	her	OBTAIN
Master		OFF
Magnetos		OFF
Fuel valve		OFF
Fire		EXTINGUISH
Use fire extinguisher, seat cushion, wool blanket, or dirt. If practical, try to remove air filter if it is ablaze		

Engine Fire During Start On Ground

Engine Fire in Flight	
Mixture	CUT-OFF
Fuel valve	OFF
Master	OFF
Cabin heat & air	OFF
(except ov	verhead vents)
Airspeed	100 KIAS
If fire is not extinguished, increase	
glide speed to find an airspeed which	
will provide an incombu	ustible mixture
Forced Landing With	EXECUTE
Engine Failure checklist	

Both cases: inspect and repair damage before conducting another flight.

Master	OFF
All other switches (except magnetos)	OFF
Vents/cabin air/heat	CLOSE
Fire extinguisher	USE
If fire appears out and electrical power	r is
necessary to continue flight:	
Master	ON
Circuit breakers	CHECK
(do not reset faulty	circuit)
Radio/electrical switches	ON
One at a time with delay after	
each until short circuit is lo	calized
Vents/cabin air/heat	OPEN

Electrical Fire in Flight

Cabin Fire	
Master	OFF
Vents/cabin air/heat	CLOSED
	(to avoid drafts)
Fire extinguisher	USE
WARNING: After discharging extinguisher	
within a closed cabin, ventilate cabin	

Land ASAP, inspect for damage

(when fire completely extinguished)

Nav lights	OF
Pitot heat	OF
NOTE: Sideslip to keep flames away from	n
fuel tanks and cabin. Land ASAP using fl	aps
only as required.	
·	

Inadvertent Icing End	ounter
Pitot heat	ON
Turn back or change alti	tude to obtain an
OAT less conducive to ic	ing.
Cabin heat	FULL ON
Defroster	OPEN
Cabin air	ADJUST
Maximize defro	ster heat and airflow
Throttle	OPEN
Carburetor/air filter icing	g MONITOR
Apply carb heat as re	equired, lean mixture
for maximum RPM if	used continuously
Land	NEAREST AIRPORT
With very rap	id ice build-up, select
	rport landing site
With $\geq 1/4$ inch ice on t	
prepare for significantly	9
Flaps	LEAVE RETRACTED
Open left window and se	•
windshield, if necessary	,
Forward slip if necessar	,
Approach speed	65-75 KIAS
' '	level of accumulation
Landing Per	form in level attitude

Static Source Blockage			
Alternate static source valve		PULL ON	
Airspeed	Use calibr	ation table	
	in POH se	ction 5	

Static Source Blockage

Landing With a riat Main Tire		
Approach	NORMAL	
Touchdown	GOOD TIRE FIRST	
Hold flat tire off ground	as long as possible	

Over-voitage Light mummates				
Master	OFF (both sides)			
Master	ON			
If over-voltage light illuminates again:				
Flight	TERMINATE ASAP			

	Ammeter Shows Discharge			
	Alternator		OFF	
	Nonessentia	I electrical equipment	OFF	
	Fliaht	TERMINATE as soon a	s practical	