ARM® Cortex®-M0

32-bit Microcontroller

# NuMicro® Family
# NUC126 Series BSP
# Revision History

*The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.*

*Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.*

*All data and specifications are subject to change without notice.*

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

## Revision 3.00.010 (Released 2026-07-06)

1. Fix BSP driver missing status check for the final 4-word write in FMC Multi-Word Program.
2. Correct the retransmission address calculation for timeout recovery in FMC Multi-Word Program.
3. Add UART_LIN_TxRx sample code.
4. Update ISP_SPI sample to add interrupt mask protection for ParseCmd.
5. Add software disconnect and reconnect API in USBD Sample code.
6. Support VSCode multi-toolchain project.
7. Add a check for the STOP bit when I2C transmission is complete.
8. USBD_HID_Mouse2: Send NAK instead of 0 to fix host not going to sleep issue.
9. Add a macro to wait for the I2C bus status to be cleared.
10. Add the macro to the sample code to avoid re-entering the interrupt before the register write is complete, which could lead to an incorrect I2C_STATUS0 value of 0xf8.

## Revision 3.00.009 (Released 2024-10-21)

1. Update SC library and fix SC sample codes run fail.
2. Add option AC=1 in the Keil project ensures that it's compiler 6.
3. Fix infinite loop.

## Revision 3.00.008 (Released 2024-05-14)

1. Remove additional UI2C Master EndFlag settings to prevent premature communication stoppage.
2. Correct UI2C Wakeup Slave and EEPROM not displaying execution results.
3. Add slew rate control for SPI sample codes.
4. Add FMC_SPROM sample code.
5. Remove USBD LPM function.
6. Modify Idrom function table locating.
7. Add process when s_Event is SLAVE_SEND_DATA after receiving SLA+R and returned ACK in USCI_I2C_Slave sample code.
8. Use "volatile" with the function pointer to disable compiler optimizations in I2C/UI2C sample code.
9. Add a reaction in TX/RX when encountering a NACK event after ARBLOIF has been triggered in UI2C_Master sample code.
10. Modify SYS_PowerDown_MinCurrent and RegBased/FMC_IAP sample code.
11. Update USBD HID keyboard sample code to support LED status.

## Revision 3.00.007 (Released 2023-09-11)

1. Modified ADC_PWMTrigger sample code print message for IAR Tiny printf formatter.
2. Modified USCI_UART_TxRx Function and FMC_IAP sample code.
3. Revised startup_NUC126.S and retarget.c to fix Hard_Fault can't run code.
4. Modified VendorName of Nu_DFU.inf.
5. Added SYS_PowerDown_MinCurrent sample code.
6. Updated SPI_Loopback sample code.
7. Updated Windows driver of USBD_Printer_And_HID_Transfer sample code.
8. Modified SYS_UnLockReg() time-out handler.
9. Fixed TX hardware FIFO size to 16 and call UART FIFO size from uart.h in USBD VCOM sample code.
10. Removed printf for PowerDown in USBD sample code.

## Revision 3.00.006 (Released 2022-08-17)

1. Revised printing error message for I2C sample code.
2. Fixed return in main() cause hardfault issue.
3. Revised infinite loop timeout handler.
4. Fixed USBD_MassStorage_CDROM crash on Linux.
5. Added I2C hang up and recover mechanism for I2C Master and Slave sample code.
6. Opened CESTOPEN in trim function of USBD sample code.
7. Updated auto trim to use SW boundary function of USBD sample code.
8. Enabled schmitt trigger of I2C sample code.
9. Fixed UART TX FIFO control issue in USBD_VCOM sample code.

## Revision 3.00.005 (Released 2021-01-21)

1. Fixed USCI_SPI driver issue in Library/StdDriver/src/usci_spi.c
2. Modified to pass USB-IF CV-Chapter 9 & Class test of all USBD Sample code.
3. Fixed USPI_SET_SS_HIGH macro in Library/StdDriver/inc/usci_spi.h
4. Corrected adc definitions for conversion sampling time selection in Library/StdDriver/inc/adc.h
5. Added Apache-2.0 license declaration in driver source.
6. Added README.md file.
7. Added SPI_TRIGGER_TX_RX_PDMA and SPI_DISABLE_TX_RX_PDMA API.

## Revision 3.00.004 (Released 2019-10-25)

1. To support GNU GCC.
2. Add emWin supporting.
3. Improve USB driver reliability.
4. Add ISP firmware sample code.

## Revision 3.00.003 (Released 2018-01-26)

1. Added CLK_SysTickLongDelay() function for long delay.
2. Improved baud rate calculation accuracy of UUART driver.
3. Improved robust of USB sample code.

## Revision 3.00.002 (Released 2017-05-05)

1. Update multi-function pin name definitions.
2. Add single byte and multi byte write/read APIs for I2C.

## Revision 3.00.001 (Released 2016-10-17)

1. Initial Release

## Important Notice

**Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".**

**Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.**

**All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.**

*Please note that all data and specifications are subject to change without notice.*
*All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*