



## NOTE

Internal Oscillator Since the error is 1%, the rightmost character varies by about half a character to the left and right, but this is acceptable.

Input video signal supports only 0–1 Vp-p.