





- 6. SILK SCR 5. SOLDER 4. DRILL HO 3. COPPER 2. BOARD T 1. 2 LAYER
- 7. PRODUCE 8. MATERIA
- 9. CUT TO C
- 10. PADS FII









## **PRODUCTION INSTRUCTIONS**

- 1. 2 LAYER BOARD
- 2. BOARD THICKNESS 1.6 mm +/- 10%
- 3. COPPER CLAD 1.0 OZ
- 4. DRILL HOLE TOLERANCE +/- 0.1%
- 5. SOLDER MASK BOTH SIDES RED
- 6. SILK SCREEN WHITE
- 7. PRODUCE PER IPC CLASS2---Apply
- 8. MATERIAL FR4
- 9. CUT TO CONTOUR
- 10. PADS FINISH: HASL

