




DETAIL A". LINTEL 3RD FLOOR. CORNER REINFORCEMENT







KNOCK-OUT CMU BOND BEAMS

DIAGRAM 02.410.0141

REV. 11/30/10

International Masonry Institute



800-IMI-0988 www.imiweb.org