

RE: Table 601 - 2009 IBC

1 message

Steve Ikkanda <sikkanda@iccsafe.org>

Wed, Sep 23, 2015 at 3:38 PM

To: "ryan@openingdesign.com" <ryan@openingdesign.com>

Cc: Renee Testroet <rtestroet@iccsafe.org>

Ryan,

September 23, 2015

Subject: Sections 603.1, 803.11.1, 803.11.2, and Table 601 - 2009 IBC

Q: We have fully sprinklered, Construction Type IIB, Group A-3 occupancy facility. We have a non-bearing exterior wall assembly with metal panels attached to horizontal metal girts and, per Table 601, it is not required to be rated. If we satisfy Section 603.1 Item 7, Interior wall and ceiling finishes installed in accordance with Sections 801 and 803 and subsequently satisfy Sections 803.11.1 and 803.11.2, then the <u>plywood</u>, as illustrated in the detail, that is exposed to the interior <u>can have the following flame spreads</u>....

Exit enclosures and exit passageways = B

Corridors = B

Rooms and enclosed spaces = C

The plywood is not integral to the structural capacity of the wall. It is simply hung/attached to the horizontal metal girds. Would this be a correct assumption? The assumption is that it meets the requirements of Section 603.1.

A: Section 602.2 requires building elements of a Type IIB building to be noncombustible material, except as permitted by Section 603. Item 7 of Section 603.1 allows combustible interior wall and ceiling finishes provided it is installed in accordance with Sections 801 and 803. Table 803.9 requires the interior wall finish for a NFPA 13 sprinklered, Group A-3 occupancy building to be tested in accordance with ASTM E 84 or UL 723 and have the following classes in accordance with their flame spread and smoke-developed indexes:

Exit enclosures and exit passageways = Class C, if less than 3 stories above grade plane and Class B, if 3 story or greater.

Corridors = Class B

Rooms and enclosed spaces = Class C.

And if the wall is required to be fire-resistance rated, then the interior finish shall comply with Section 803.11.

Code opinions issued by ICC staff are based on ICC-published codes and do not include local, state or federal codes, policies or amendments. This opinion is based on the information which you have provided. We have made no independent effort to verify the accuracy of this information nor have we conducted a review beyond the scope of your question. This opinion does not imply approval of an equivalency, specific product, specific design, or specific installation and cannot be published in any form implying such approval by the International Code Council. As this opinion is only advisory, the final decision is the responsibility of the designated authority charged with the administration and enforcement of this code.

"Copyright © 2015 International Code Council, Inc. All rights reserved."

Steve Ikkanda

Senior Staff Engineer

Architectural & Engr Services

International Code Council

Western Regional Office

3060 Saturn Street, Suite 100

Brea, CA 92821

Phone: (888) 422-7233, Ext 3997

Fax: (562) 699-4522

From: Renee Testroet

Sent: Wednesday, September 23, 2015 9:46 AM

To: ryan@openingdesign.com

Cc: Steve Ikkanda

Subject: Table 601 - 2009 IBC

Ryan,

I have forwarded your code opinion request to Steve Ikkanda.

Please let me know if you have any questions.

Renee Testroet

Senior Secretary II

International Code Council

Chicago District Office

4051 W. Flossmoor Road

Country Club Hills, IL 60478

rtestroet@iccsafe.org

Phone: (888) 422-7233, Ext. 4312

Fax: (708) 799-0310

Join us for the International Code Council 2015 Annual Conference, Public Comment Hearings & Expo Sept. 27 – Oct. 5, in Long Beach, Calif. This event offers more than 20 educational sessions to earn CEUs and LUs, certification testing, building tours, networking and more. Register Today!