


Alarm ER. 731 or ER. 730

Parameter setting **H0D-20=1**

- 1: press SET, exit the alarm
- 2: press mode (show H00)
- 3: press UP until it turns to H0D (14 times)
- 4: press SET(show H0D.00)



- 6: press  for one time
- 7: press UP turn to H0D.20
- 8: press SET, (show 0)
- 9: press UP to 1 (H0D-20=1)
- 10: press SET, parameter has been successfully when it shows done,
- 11: press MODE to return.