TECH SOLUTIONS
Appliance Repair Service

Tech Solutions Repair Service Inc.
51 Majestic Ct, Apt 904, Moorpark, CA 93021
Serving Moorpark & Ventura County
(805) 991-2874
tsrepairservice.com
State Registration No. A 50537 (BHGS)

ESTIMATE.

ESTIMATE NO.	DATE	VALID UNTIL
TS-E-2026-0001	Oct 13, 2026	Oct 20, 2026

CUSTOMER

Sample Customer
123 Sample Street
Moorpark, CA 93021
(805) 555-0100
customer@example.com

APPLIANCE

Washer (top load)
Whirlpool WTW4950XW2
S/N XXXXXXXXXX

REPORTED PROBLEM

Tub shakes and bounces during spin cycle.

Findings: Worn suspension rods.

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
SERVICE CALL, TRAVEL & LABOR			
Service call / diagnostic fee	1	$95.00	$95.00
Labor: replace suspension rods	1	$120.00	$120.00
PARTS			
Suspension rod kit (set of 4) Part # W10780051	1	$52.00	$52.00

DIAGNOSTIC / SERVICE CALL

The $95.00 service call / diagnostic fee is included in the estimate total, not charged extra. If you decline the repair, only $95.00 is due.

WARRANTY

Guarantor: Tech Solutions Repair Service Inc. Labor is guaranteed for 30 days and parts installed for 90 days from the date of service. The guarantee covers the repair performed and the parts installed; it does not cover other components or damage caused by misuse.

TAXES

Sales tax and other applicable taxes are not included in this estimate.

Service call & labor	$215.00
Parts	$52.00
Estimate total	**$267.00**

CUSTOMER AUTHORIZATION

I received this written estimate and authorize the repairs described above. The service dealer may not charge for work done or parts supplied above this estimate total without my prior consent.

Customer signature _____ Printed name _____ Technician (signature or employee no.) _____ Date / time _____

REVISED ESTIMATE / CHANGE AUTHORIZATION (use if the cost increases; get the customer's consent first)

Date / time _____ Added or changed work and parts _____ New total _____ Approved by (signature, or name + phone if oral) _____

An estimate as required (Section 9844 of the California Business and Professions Code) for repairs shall be given to the customer by the service dealer in writing, and the service dealer may not charge for work done or parts supplied in excess of the estimate without prior consent of the customer. Where provided in writing, the service dealer may charge a reasonable fee for services provided in determining the nature of the malfunction in preparation of a written estimate for repair. For information contact the Bureau of Household Goods and Services, Department of Consumer Affairs, Sacramento 95834.

Thank you for choosing Tech Solutions Repair Service!
(805) 991-2874 · tsrepairservice.com

SAMPLE