

$$\omega_{m}$$
Symbol descriptions
$$\omega_{m}^{*} \text{ reference speed } i_{s} \text{ stator current } u_{a}, u_{b}, u_{c} \text{ phase voltages } \omega_{m} \text{ measured speed } i_{q}^{*} \text{ reference current } i_{q}^{corr} \text{ compensation } e_{i} \text{ speed error } u^{*} \text{ reference voltage } \theta_{m} \text{ rotor angle }$$